

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402890468

Receive Date:

12/07/2021

TRANSFER OF OPERATORSHIP

A Selling Operator will notify the Commission about the transfer of any Transferable Item associated with its Oil and Gas Operations to a Buying Operator by filing a Form 9, Transfer of Operatorship – Intent, with the Commission at least 30 days, or as soon as practicable, before the anticipated transfer date. (Rule 218.b.) When a transaction subject to a Form 9 – Intent becomes final, the Buying Operator will submit a Form 9 – Subsequent within 7 days of closing. (Rule 218.d.(1).)

Type of Form 9, Transfer of Operatorship: Intent **Subsequent** Intent # 402847248

OPERATOR INFORMATION

SELLING OPERATOR INFORMATION

OGCC Operator Number: 16700 Contact Name and Telephone:
 Name of Operator: CHEVRON USA INC Name: Jimmy Lozano
 Address: 100 CHEVRON ROAD Phone: (432) 687-7696
 City: RANGELY State: CO Zip: 81648 Email: jimmy.lozano@chevron.com

BUYING OPERATOR INFORMATION

OGCC Operator Number: 10779 Contact Name and Telephone:
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC Name: Tee Brown
 Address: 13800 MONTFORT DRIVE SUITE 100 Phone: (972) 325-1027
 City: DALLAS State: TX Zip: 75240 Email: tbrown@scoutep.com

TRANSFER INFO

Transfer Dates

Form 9 Intent - Anticipated Date of Transfer: 12/01/2021
 Form 9 Subsequent - Effective Date of Transfer: s12/01/2021

Confidentiality

Transfer is Confidential: No

Financial Assurance

Form 9 Intent - Estimated amount of Financial Assurance the Buying Operator will submit prior to anticipated date of transfer: \$ 100,000
 Form 9 Subsequent - The Buying Operator's Financial Assurance:

Surety ID	Bond Type	Amount
20210101	PLUGGING	100,000
20210100	SURFACE	25,000
20210104	INDIVIDUAL	470,000
20210103	PLUGGING	3,500,000

SUBSEQUENT LIABILITY

Rule 218.d.(1).D.i.

"For Transferable Items listed in Rule 218.d.(1).B.i an acknowledgment that upon the effective date of transfer, that the Buying Operator assumes all responsibility for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.i.

Rule 218.d.(1).D.ii.

"For Transferable Items listed in Rule 218.d.(1).B.ii or iii, an acknowledgment that the Buying Operator may be or may become responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders if the Buying Operator takes any action, or fails to take any action, that would cause such Transferable Item to be out of compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.ii.

Rule 218.d.(1).D.iii.

"For Transferable Items not listed in Rule 218.d.(1).B.i-iii but Related in the Commission's records, an acknowledgment that the Commission will presume that the Transferable Item was transferred, and that the Buying Operator is responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.iii.

SUBMITTAL

OPERATOR COMMENT AND SUBMITTAL

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tee Brown Email: tbrown@scoutep.com

Signature: _____ Title: Regulatory Manager Date: 12/07/2021

Wells & Facilities Transferred Summary

1	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314368	314368	CARNEY-62N102W #34NWSE	NWSE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
2	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-05482	228585	314368	CARNEY #1-34	NWSE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
3	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314369	314369	MCLAUGHLIN, S W-62N102W #33NWSE	NWSE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
4	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-05483	228586	314369	MCLAUGHLIN, S W #1	NWSE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
5	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314370	314370	EMERALD-62N103W #36SENE	SENE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
6	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-05488	228590	314370	EMERALD #36	SENE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
7	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314371	314371	UNION PACIFIC-62N102W #34NWSW	NWSW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
8	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-05489	228591	314371	UNION PACIFIC #B 1-34	NWSW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
9	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	314372	314372	E RECTOR-62N102W #34NESE	NESE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					

	RIO BLANCO		16700	CHEVRON USA INC					
10	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05494	228592	314372	E RECTOR #1	NESE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
11	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314373	314373	EMERALD-62N103W #36NENE	NENE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
12	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05505	228597	314373	EMERALD #4	NENE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
13	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314375	314375	U P-62N102W #34SWNW	SWNW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
14	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05510	228599	314375	U P #3-34	SWNW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
15	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314376	314376	FEE-62N102W #33SENE	SENE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
16	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05511	228600	314376	FEE #9	SENE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
17	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314377	314377	EMERALD-62N103W #36NWNE	NWNE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
18	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05512	228601	314377	EMERALD #37	NWNE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

19	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314378	314378	S H MCLAUGHLIN GOV-62N102W #33SWNE	SWNE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
20	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05513	228602	314378	S H MCLAUGHLIN GOV #1-33	SWNE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
21	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314379	314379	CARNEY-62N102W #34SENE	SENE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
22	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05514	228603	314379	CARNEY #2-34	SENE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
23	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314381	314381	EMERALD-62N103W #36SWNE	SWNE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
24	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05558	228614	314381	EMERALD #20	SWNE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
25	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314382	314382	EMERALD-62N103W #36NENW	NENW	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
26	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05565	228619	314382	EMERALD #14	NENW	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
27	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314383	314383	UNION PACIFIC-62N102W #32NENW	NENW	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					

28	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05567	228620	314383	UNION PACIFIC #1-32	NENW	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
29	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05568	228621	314384	FEE #15	NENE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
30	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314386	314386	FV LARSON-62N102W #36NWNW	NWNW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
31	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05579	228626	314386	FV LARSON #B-13X	NWNW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
32	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314388	314388	EMERALD-62N103W #25SWSE	SWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
33	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05588	228632	314388	EMERALD #6	SWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
34	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314389	314389	EMERALD-62N103W #25SWSW	SWSW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
35	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05589	228633	314389	EMERALD #23	SWSW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
36	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314390	314390	EMERALD-62N103W #26NESE	NESE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					

37	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05590	228634	314390	EMERALD #8	NESE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
38	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314391	314391	LEVISON-62N102W #27SESE	SESE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
39	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05591	228635	314391	LEVISON #1	SESE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
40	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314392	314392	STOFFER, C R-62N103W #26SWSE	SWSE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
41	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05592	228636	314392	STOFFER, C R #A-2	SWSE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
42	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314393	314393	LEVISON-62N102W #26SWSW	SWSW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
43	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05593	228637	314393	LEVISON #2	SWSW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
44	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314394	314394	EMERALD-62N103W #25SESW	SESW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
45	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05594	228638	314394	EMERALD #35	SESW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

46	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314395	314395	EMERALD-62N103W #25SESE	SESE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
47	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05595	228639	314395	EMERALD #34	SESE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
48	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314396	314396	FEE-62N102W #28SWSE	SWSE	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
49	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05596	228640	314396	FEE #11	SWSE	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
50	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314397	314397	EMERALD-62N102W #30SWSW	SWSW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
51	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05599	228643	314397	EMERALD #3	SWSW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
52	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314398	314398	S MCLAUGHLIN-62N102W #28SWSW	SWSW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
53	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05600	228644	314398	S MCLAUGHLIN #2-28	SWSW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
54	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314399	314399	SHARPLES-MCLAUGHLIN-62N102W #28SESW	SESW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					

55	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05603	228645	314399	SHARPLES-MCLAUGHLIN #1-28	SESW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
56	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314401	314401	STOFFER, C R-62N103W #26NWSE	NWSE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
57	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05627	228664	314401	STOFFER, C R #A-1	NWSE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
58	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314402	314402	EMERALD-62N103W #25NESW	NESW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
59	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05628	228665	314402	EMERALD #28	NESW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
60	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314403	314403	EMERALD-62N102W #30NESW	NESW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
61	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05631	228667	314403	EMERALD #1	NESW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
62	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314404	314404	UNION PACIFIC-62N102W #29NESW	NESW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
63	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05632	228668	314404	UNION PACIFIC #4-29	NESW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

64	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314405	314405	FEE-62N102W #29NESE	NESE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
65	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05633	228669	314405	FEE #8	NESE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
66	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314406	314406	EMERALD-62N103W #26SENE	SENE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
67	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05636	228672	314406	EMERALD #13	SENE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
68	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314407	314407	U P R R-62N102W #28NESW	NESW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
69	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05639	228674	314407	U P R R #5-28	NESW	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
70	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314409	314409	RAVEN-62N102W #30SWNE	SWNE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
71	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05649	228682	314409	RAVEN #B-1	SWNE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
72	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314410	314410	FEE-62N102W #28SWNE	SWNE	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
73	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	WELL	103-05651	228684	314410	FEE #12	SWNE	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
74	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314411	314411	EMERALD-62N103W #25SWNW	SWNW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
75	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05653	228686	314411	EMERALD #27	SWNW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
76	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314412	314412	NEAL-62N103W #25SENV	SENV	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
77	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05655	228688	314412	NEAL #4	SENV	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
78	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314413	314413	UNION PACIFIC-62N102W #29SWNE	SWNE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
79	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05656	228689	314413	UNION PACIFIC #9-29	SWNE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
80	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314414	314414	FEE-62N102W #29SWNW	SWNW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
81	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05657	228690	314414	FEE #3	SWNW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
82	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314415	314415	NEAL-62N103W #25SWNE	SWNE	25	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
83	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05659	228692	314415	NEAL #5A	SWNE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
84	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314416	314416	EMERALD-62N103W #26SWNE	SWNE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
85	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	117204	314416	EMERALD "C" 171 #	SWNE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
86	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05661	228694	314416	EMERALD #9	SWNE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
87	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05662	228695	314417	EMERALD #10	NENE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
88	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314418	314418	LARSON, M B-62N103W #26SWNW	SWNW	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
89	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05663	228696	314418	LARSON, M B #A-2-26	SWNW	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
90	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314419	314419	FEE-62N102W #29NENE	NENE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
91	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	116970	314419	FEE CENTRAL DISPOSAL #	NENE	29	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
92	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05668	228701	314419	FEE #10	NENE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
93	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314420	314420	EMERALD-62N103W #25NENE	NENE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
94	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05669	228702	314420	EMERALD #2	NENE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
95	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314421	314421	EMERALD-62N103W #26NWNE	NWNE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
96	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05671	228703	314421	EMERALD #11	NWNE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
97	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314422	314422	NEAL-62N103W #25NENW	NENW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
98	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05672	228704	314422	NEAL #3	NENW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
99	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314423	314423	STOFFER, C R-62N103W #26NWNW	NWNW	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
100	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05673	228705	314423	STOFFER, C R #B-1	NWNW	26	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
101	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314424	314424	FEE-62N102W #29NWNW	NWNW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
102	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05674	228706	314424	FEE #52	NWNW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
103	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314425	314425	EMERALD-62N103W #26SESE	SESE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
104	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05677	228708	314425	EMERALD #17	SESE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
105	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314427	314427	FEE-62N102W #22SESW	SESW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
106	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05683	228711	314427	FEE #68A	SESW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
107	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314428	314428	U P-62N102W #21SWSE	SWSE	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
108	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05685	228712	314428	UNION PACIFIC #10-21	SWSE	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
109	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314429	314429	U P R R-62N102W #20SWSW	SWSW	20	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
110	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05686	228713	314429	U P R R #8-20	SWSW	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
111	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314430	314430	FEE-62N102W #21SWSW	SWSW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
112	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05687	228714	314430	FEE #14	SWSW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
113	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314431	314431	FEE-62N102W #20SESE	SESE	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
114	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05688	228715	314431	FEE #42	SESE	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
115	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314432	314432	S B LACY-62N103W #24SWSW	SWSW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
116	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05689	228716	314432	S B LACY #3	SWSW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
117	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314433	314433	LARSON, M B-62N103W #22SESE	SESE	22	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
118	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05690	228717	314433	LARSON, M B #C-2	SESE	22	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
119	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314434	314434	HAGOOD L N-62N103W #23SWSE	SWSE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
120	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05691	228718	314434	HAGOOD L N #A-8	SWSE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
121	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314435	314435	U P R R-62N102W #20SWSE	SWSE	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
122	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05692	228719	314435	U P R R #2-20	SWSE	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
123	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314436	314436	A.C. MCLAUGHLIN (RE-ENTRY-62N103W #23SESW	SESW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
124	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05693	228720	314436	A.C. MCLAUGHLIN (RE-ENTRY #11)	SESW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
125	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314437	314437	HAGOOD L N-62N103W #23SESE	SESE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
126	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	117208	314437	RANGELY WEBER SAND UNIT 4 #	SESE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
127	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	WELL	103-05694	228721	314437	HAGOOD L N #A-6	SESE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
128	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314438	314438	UNION PACIFIC-62N102W #21SESW	SESW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
129	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05696	228723	314438	UNION PACIFIC #45-21	SESW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
130	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314439	314439	RIGBY-62N103W #24SWSE	SWSE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
131	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05697	228724	314439	RIGBY #1	SWSE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
132	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314440	314440	MCLAUGHLIN-62N103W #23SWSW	SWSW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
133	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05699	228725	314440	MCLAUGHLIN #28	SWSW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
134	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314441	314441	HAGOOD L N-62N103W #23NWSE	NWSE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
135	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05707	228731	314441	HAGOOD L N #A-4	NWSE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
136	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	314442	314442	M.B. LARSON C-62N103W #22NWSE	NWSE	22	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
137	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05708	228732	314442	M.B. LARSON C #3	NWSE	22	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
138	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314443	314443	A C MCLAUGHLIN-62N103W #23NESW	NESW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
139	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05712	228735	314443	A C MCLAUGHLIN #5	NESW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
140	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314444	314444	ASSOCIATED-62N103W #24NESW	NESW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
141	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05713	228736	314444	ASSOCIATED #A-1	NESW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
142	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314445	314445	ASSOCIATED(SIDE TRACK)-62N103W #24NWSE	NWSE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
143	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05714	228737	314445	ASSOCIATED(SIDE TRACK) #A-2	NWSE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
144	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314446	314446	GRAY-62N103W #24NESE	NESE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
145	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	WELL	103-05715	228738	314446	GRAY #A-9	NESE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
146	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314447	314447	MCLAUGHLIN, A C-62N103W #23NWSW	NWSW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
147	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	117217	314447	RANGELY WEBER SAND UNIT 4 #	NWSW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
148	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05718	228741	314447	MCLAUGHLIN, A C #23	NWSW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
149	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	314448	314448	FEE-62N102W #20NESE	NESE	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
150	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-05720	228743	314448	FEE #6	NESE	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

Incidents Transferred Summary

1	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	675100848	INSPECTION WITH CORRECTIVE ACTION	12/26/2014	16700	CHEVRON USA INC
2	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679705014	INSPECTION WITH CORRECTIVE ACTION	08/08/2019	16700	CHEVRON USA INC
3	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679705349	INSPECTION WITH CORRECTIVE ACTION	09/05/2019	16700	CHEVRON USA INC
4	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679705353	INSPECTION WITH CORRECTIVE ACTION	09/06/2019	16700	CHEVRON USA INC
5	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679705409	INSPECTION WITH CORRECTIVE ACTION	09/11/2019	16700	CHEVRON USA INC

6	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706188	INSPECTION WITH CORRECTIVE ACTION	11/20/2019	16700	CHEVRON USA INC
7	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706397	INSPECTION WITH CORRECTIVE ACTION	12/03/2019	16700	CHEVRON USA INC
8	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706405	INSPECTION WITH CORRECTIVE ACTION	12/03/2019	16700	CHEVRON USA INC
9	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679706743	INSPECTION WITH CORRECTIVE ACTION	12/30/2019	16700	CHEVRON USA INC
10	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679707086	INSPECTION WITH CORRECTIVE ACTION	01/24/2020	16700	CHEVRON USA INC
11	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	679707239	INSPECTION WITH CORRECTIVE ACTION	02/05/2020	16700	CHEVRON USA INC
12	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	693800494	INSPECTION WITH CORRECTIVE ACTION	06/03/2019	16700	CHEVRON USA INC
13	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	696202362	INSPECTION WITH CORRECTIVE ACTION	02/19/2021	16700	CHEVRON USA INC
14	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	700403168	INSPECTION WITH CORRECTIVE ACTION	08/28/2020	16700	CHEVRON USA INC
15	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701102154	INSPECTION WITH CORRECTIVE ACTION	10/29/2021	16700	CHEVRON USA INC
16	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701103273	INSPECTION WITH CORRECTIVE ACTION	06/27/2022	16700	CHEVRON USA INC
17	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500320	INSPECTION WITH CORRECTIVE ACTION	04/13/2021	16700	CHEVRON USA INC
18	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500527	INSPECTION WITH CORRECTIVE ACTION	04/28/2021	16700	CHEVRON USA INC
19	<u>Document Numbers</u>	<u>Incident Type</u>	<u>Incident Date</u>	<u>Current Op #</u>	<u>Current Op. Name</u>
	701500529	INSPECTION WITH CORRECTIVE ACTION	04/28/2021	16700	CHEVRON USA INC

Related Wells & Facilities Not Transferred Summary

< No row provided >

Related Incidents Not Transferred Summary

< No row provided >

Wells & Facilities Proposed Not Transferred Summary

< No row provided >

Incidents Proposed Not Transferred Summary

< No row provided >

Attachment List

Att Doc Num	Name
1585513	CORRESPONDENCE
1585514	CORRESPONDENCE
1585515	BUYER NOTIFIED LOCAL GOVT ATTESTATION
402890468	Form 09 SUBMITTED
402890483	FORM 9 SUBSEQUENT ATTESTATION
403315930	EDD-S-INCIDENTS-TRANSFERRED
403315936	EDD-S-WELLS-FACILITIES-TRANSFERRED

Total Attach: 7 Files

COA Type

Description

0 COA

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Financial Assurance	Both operators have resolved all issues and accepted the COAs. Form 9 approved.	04/13/2023
Financial Assurance	<p>Here is where we currently stand. It appears that the Spill or Releases are the issue. They need to be entered correctly on the spreadsheet.</p> <p>Chevron #40284700 to Scout #402887795</p> <p>· Location ID #311804 Union Pacific #34-31 Facility ID #444035 Spill or Release AC - 2/5/2021 This is an active Spill or Release and needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847248 to Scout #402890468</p> <p>· There is one Unaccounted For Facility (Location #314373, EMERALD #4 Facility # 480349 Emerald 4 Flowline spill - AC 8/2/2021) that needs to be accounted for. 2021 This is an active Spill or Release and needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847267 to Scout #402890493</p> <p>· There is one Unaccounted For Facility (Location #314622 FEE #19, Facility # 448608 SPILL/RELEASE POINT -AC 4/12/2021) that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847273 to Scout #402890516</p> <p>· There is one Unaccounted For Facility (Location #314646 UNION PACIFIC #22-32 , Facility # 453683 Spill – AC 2-5-2021) that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847276 to Scout #402890528</p> <p>· There is one Unaccounted For Spill or Release (Location #314763 (M B LARSON #C11 X 25 well P&A 8/24/2021) location active open remediation , Facility # 481149 – SPILL satellite header 38 bulk line-AC 12/1/2021) that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847277 to Scout #402891430</p> <p>There are two Unaccounted For Facilities that need to be accounted for as follows: Location ID #314933 Facility ID #438685 Spill or Release Location ID #314965 Facility ID #480932 Spill or Release</p> <p>The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847282 to Scout #402891448</p> <p>There is one Unaccounted For Facility (Location #315324, Facility # 481858) that is a Spill and Release point that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847287 to Scout #402891495</p> <p>There is one Unaccounted For Facility (Location #315740, Facility # 447266) that is a Spill and Release point that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.</p> <p>Chevron #402847293 to Scout #402891516</p>	02/08/2023

There is one Unaccounted For Facility (Location #316136, Facility # 446036) that is a Spill and Release point that needs to be accounted for. The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively.

Chevron #402847328 to Scout #402891662

There are five Unaccounted For Facilities that need to be accounted for as follows:

- Location ID #413288 Facility ID #448925 Spill or Release
- Location ID #413288 Facility ID #457749 Spill or Release
- Location ID #426403 Facility ID #481872 Flowline System
- Location ID #426403 Facility ID #483023 Spill or Release
- Location ID #451320 Facility ID #451090 Spill or Release

The Facility Type in Column B is Spill or Release with the Facility ID and Location ID in columns E and F respectively. Instead of Location, Location ID 426403, Facility ID 481872 should have Flowline System as the Facility Type in Column B.

Assuming the other Form 9 requirements are met, all Form 9s shall now be passed with the following two COAs:

The Buying Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Buyer will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

The Selling Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Seller will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

Please note that each operator needs confirm that it will abide by the aforementioned COA by responding to this email. The correspondence will be uploaded to the form.

Please reach out with any questions.

Financial Assurance

I am reviewed the transfer again with the following issues noted below.

11/23/2022

Chevron #40284700 to Scout #402887795

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are two Unaccounted For Facilities that need to be accounted for as follows:

o Location ID #311804 Facility ID #444035 Spill or Release

o Location ID #314367 Facility ID #314367

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 20 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

1. If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

2. If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847248 to Scout #402890468

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There is one Unaccounted For Facility (Location #314373, Facility # 480349) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 19 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847259 to Scout #402890487

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847267 to Scout #402890493

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There is one Unaccounted For Facility (Location #314622, Facility # 448608) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 18 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847273 to Scout #402890516

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314646, Facility # 453683) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 21 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847276 to Scout #402890528

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314763, Facility # 481149) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 40 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847277 to Scout #402891430

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are two Unaccounted For Facilities that need to be accounted for as follows:

- o Location ID #314933 Facility ID #438685 Spill or Release

- o Location ID #314965 Facility ID #480932 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847282 to Scout #402891448

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #315324, Facility # 481858) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 29 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847287 to Scout #402891495

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #315740, Facility # 447266) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847293 to Scout #402891516

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #316136, Facility # 446036) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 28 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847295 to Scout #402891587

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847312 to Scout #402891604

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 6 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847322 to Scout #402891631

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are 7 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847328 to Scout #402891662

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

· There are five Unaccounted For Facilities that need to be accounted for as follows:

o Location ID #413288 Facility ID #448925 Spill or Release

o Location ID #413288 Facility ID #457749 Spill or Release

o Location ID #426403 Facility ID #481872 Flowline System

o Location ID #426403 Facility ID #483023 Spill or Release

o Location ID #451320 Facility ID #451090 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 19 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847336 to Scout #402891690

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847928 to Scout #402891710

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847952 to Scout #402891752

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Assuming the other Form 9 requirements are met, all Form 9s shall now be passed with the following two COAs:

The Buying Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Buyer will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission’s approval of the Form 3, Financial Assurance Plan.

The Selling Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Seller will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission’s approval of the Form 3, Financial Assurance Plan.

Please note that each operator needs confirm that it will abide by the aforementioned COA by responding to this email. The correspondence will be uploaded to the form.

If the operators have submitted a Form 3, please provide the following comment when submitting the revised Form 3.

Form 3 Document #____ is submitted as a result of an approved Form 9 Transfer of Operatorship and it replaces Form 3 document # _____.

Please reach out with any questions.

Thanks,

Deb

Financial Assurance

I have reviewed all 17 pairs of Intent and Subsequent documents involved in your transfer. I have noted below some issues that will need to be resolved before we can approve the transfer.

04/01/2022

Problem 1: For the following 15 Subsequent documents (402887795, 402890468, 402890487, 402890493, 402890516, 402890528, 402891430, 402891448, 402891495, 402891516, 402891587, 402891604, 402891631, 402891662 and 402891690), the Wells and Facilities Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.

Solution 1: Please resubmit all 15 of the Wells and Facilities Transferred spreadsheets listing the current operator reflected in COGIS.

Problem 2: For the last two Subsequent documents (402891710 and 402891752), the Incidents Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.

Solution 2: Please resubmit both of the Incidents Transferred spreadsheets for subsequent document #402891710 and #402891751 listing the current operator reflected in COGIS.

Problem 3: There are Related Wells and Facilities that are not accounted for in the transfer.

Solution 3: I have attached a workbook that lists the Related Wells and Facilities that are not accounted for. In order for the transfer to be approved, the Related Wells and Facilities must be accounted for by one or a combination of the following options:

Solution 3a: Add the well and location to the Wells and Facilities Transferred list in the Subsequent.

Solution 3b: Generate and submit a Related Wells and Facilities – Not Transferred List. If

not transferring the wells and facilities, the COGCC will also require a Seller Retains Responsibility Attestation. Guidance for this attestation can also be found in the attachment.

Problem 4: In the same workbook as referenced in Problem 3, there is a list of Related Incidents that are not accounted for. Most of these incidents are Unresolved Field Inspections with Corrective Actions. These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or both of the following ways.

Solution 4a: If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

Solution 4b: If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

For both Problems 3 and 4 the lists include Unresolved Spill/Release. If the Spill/Release is closed, the COGCC does not require that the Spill/Release be transferred. It is up to the operators to determine whether or not they should be transferred. All revised and new documents can be emailed to me and I will upload them to Subsequent #402891752.

Please reach out with any questions.

Total: 4 comment(s)