

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403358258

Date Received:
03/28/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 6 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		RangelyRegulatory@scoutep.com
.		dnr_cogccenforcement@state.co.us
Neidel, Kris		kris.neidel@state.co.us
Olson, Andrew	(970) 257-6079	andrewolson@chevron.com
Fischer, Alex		alex.fischer@state.co.us
Sanford, Anita		Anita.Sanford@scoutep.com
Patterson, Chris		Chris.Patterson@scoutep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204793

Inspection Date: 03/24/2023

FIR Submit Date: 03/27/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314697

Location Name: MCLAUGHLIN, A C-62N103W Number: 14SESW County: _____

Qtrqtr: SESW Sec: 14 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.139490 Longitude: -108.928130

FACILITY - API Number: 05-103- -00 Facility ID: 314697

Facility Name: MCLAUGHLIN, A C-62N103W Number: 14SESW

Qtrqtr: SESW Sec: 14 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.139490 Longitude: -108.928130

CORRECTIVE ACTIONS:

1 CA# 168597

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Date: 03/25/2023

Fluids observed mixing with stormwater/wet soils- unable to determination of spill volume; Operator will contact COGCC EPS Staff for direction regarding any Rule 912.b spill reporting requirements no later than 3/30/2023.

Response: CA COMPLETED Date of Completion: 03/25/2023

Operator Comment: Cap was installed on pump. Area has been cleaned up. Contacted Kris Neidel with the COGCC about the Spill 3/28/2023 @ 12:20PM

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed; no details provided regarding spill clean up. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 168598

Corrective Action: Implement BMPs and properly store equipment in a manner that minimizes pollution. Any impacted soils will require cleaning to Table 915-1 and/or proper disposal. Date: 04/03/2023

Response: CA COMPLETED Date of Completion: 03/28/2023

Operator Comment: Removed equipment, cleaned area and will store equipment on or in containment going forward.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 CA# 168599

Corrective Action: Comply with Rule 605.h Date: 04/24/2023

Response: CA COMPLETED Date of Completion: 03/28/2023

Operator Comment: Signage and labels replace

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 CA# 168600

Corrective Action: Comply with Rule 606. Date: 04/06/2023

Response: CA COMPLETED Date of Completion: 03/28/2023

Operator Comment: Trash Removed

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

5 CA# 168601

Corrective Action: Remove and properly store any equipment currently stored beyond the designated working pad area. Date: 03/31/2023

Response: CA COMPLETED Date of Completion: 03/28/2023

Operator Comment: Removed and will be stored properly

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attachment

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: _____

Title: Sr. HSE Coordinator

Date: 3/28/2023 12:59:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403358258	FIR RESOLUTION SUBMITTED
403358277	PIC
403358311	PIC
403358358	PIC
403358361	PIC
403358362	PIC

Total Attach: 6 Files