

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402847282

Receive Date:

11/10/2021

TRANSFER OF OPERATORSHIP

A Selling Operator will notify the Commission about the transfer of any Transferable Item associated with its Oil and Gas Operations to a Buying Operator by filing a Form 9, Transfer of Operatorship – Intent, with the Commission at least 30 days, or as soon as practicable, before the anticipated transfer date. (Rule 218.b.) When a transaction subject to a Form 9 – Intent becomes final, the Buying Operator will submit a Form 9 – Subsequent within 7 days of closing. (Rule 218.d.(1).)

Type of Form 9, Transfer of Operatorship: ☒ **Intent** ☐ **Subsequent** Intent # _____

OPERATOR INFORMATION

SELLING OPERATOR INFORMATION

OGCC Operator Number: 16700 Contact Name and Telephone:
Name of Operator: CHEVRON USA INC Name: Jimmy Lozano
Address: 100 CHEVRON ROAD Phone: (432) 687-7696
City: RANGELY State: CO Zip: 81648 Email: jimmy.lozano@chevron.com

BUYING OPERATOR INFORMATION

OGCC Operator Number: 10779 Contact Name and Telephone:
Name of Operator: SCOUT ENERGY MANAGEMENT LLC Name: Tee Brown
Address: 13800 MONTFORT DRIVE SUITE 100 Phone: (972) 325-1027
City: DALLAS State: TX Zip: 75240 Email: tbrown@scoutep.com

TRANSFER INFO

Transfer Dates

Form 9 Intent - Anticipated Date of Transfer: 12/01/2021

Form 9 Subsequent - Effective Date of Transfer: _____ s

Confidentiality

Transfer is Confidential: No

Financial Assurance

Form 9 Intent - Estimated amount of Financial Assurance the Buying Operator will submit prior to anticipated date of transfer: \$ 100,000

Form 9 Subsequent - The Buying Operator's Financial Assurance:

SUBSEQUENT LIABILITY

Rule 218.d.(1).D.i.

"For Transferable Items listed in Rule 218.d.(1).B.i an acknowledgment that upon the effective date of transfer, that the Buying Operator assumes all responsibility for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.i. ☐

Rule 218.d.(1).D.ii.

"For Transferable Items listed in Rule 218.d.(1).B.ii or iii, an acknowledgment that the Buying Operator may be or may become responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders if the Buying Operator takes any action, or fails to take any action, that would cause such Transferable Item to be out of compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.ii. ☐

Rule 218.d.(1).D.iii.

"For Transferable Items not listed in Rule 218.d.(1).B.i-iii but Related in the Commission's records, an acknowledgment that the Commission will presume that the Transferable Item was transferred, and that the Buying Operator is responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.iii. ☐

SUBMITTAL

OPERATOR COMMENT AND SUBMITTAL

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Julie Webb Email: julie.webb@chevron.com

Signature: Title: Sr. Regulatory Analyst Date: 11/10/2021

Wells & Facilities Proposed for Transfer Summary

1	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315120	315120	LACY S B-62N103W #24NWSW	NWSW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
2	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07947	230287	315120	LACY S B #6X	NWSW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
3	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315121	315121	EMERALD-62N103W #25SE	SE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
4	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07948	230288	315121	EMERALD #65X	CSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
5	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315122	315122	HAGOOD L N-62N103W #23SWNE	SWNE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
6	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07949	230289	315122	HAGOOD L N #A-11X	SWNE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
7	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315123	315123	HAGOOD L N-62N103W #23SWNE	SWNE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
8	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07950	230290	315123	HAGOOD LN A #14X	SWNE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
9	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315124	315124	CHEVRON FEE-62N102W #19NESE	NESE	19	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					

	RIO BLANCO		16700	CHEVRON USA INC					
10	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07952	230292	315124	CHEVRON FEE #108X	NESE	19	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
11	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315133	315133	UNION PACIFIC-62N102W #20NWSE	NWSE	20	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
12	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07973	230313	315133	UNION PACIFIC #101 X 20	NWSE	20	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
13	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315134	315134	EMERALD-62N102W #30NESW	NESW	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
14	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07974	230314	315134	EMERALD #67X	NESW	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
15	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315135	315135	EMERALD-62N102W #30SENV	SENV	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
16	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07975	230315	315135	EMERALD #68X	SENV	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
17	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315137	315137	UNION PACIFIC-62N102W #20SWSE	SWSE	20	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
18	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07977	230317	315137	UNION PACIFIC #102X-20	SWSE	20	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					

	RIO BLANCO	FEE		16700	CHEVRON USA INC				
19	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315138	315138	LACY, S B-62N103W #24NWSW	NWSW	24	2N	103W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
20	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07978	230318	315138	LACY, S B #7X	NWSW	24	2N	103W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
21	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315147	315147	FEE-62N102W #19SESW	SESW	19	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
22	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07989	230329	315147	FEE #109X	SESW	19	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
23	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315148	315148	UNION PACIFIC-62N102W #20SESW	SESW	20	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
24	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07990	230330	315148	UNION PACIFIC #103X-20	SESW	20	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
25	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315149	315149	HAGOOD L N-62N103W #23SWSE	SWSE	23	2N	103W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
26	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07991	230331	315149	HAGOOD L N #A-13X	SWSE	23	2N	103W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
27	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315150	315150	EMERALD-62N103W #26NENE	NENE	26	2N	103W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				

	RIO BLANCO		16700	CHEVRON USA INC					
28	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-07992	230332	315150	EMERALD #64X	NENE	26	2N	103W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
29	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315163	315163	ASSOCIATED-62N103W #24NESW	NESW	24	2N	103W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
30	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-08011	230349	315163	ASSOCIATED #A-6X	NESW	24	2N	103W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
31	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315172	315172	FEE-62N102W #19NESW	NESW	19	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
32	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-08026	230364	315172	FEE #110X	NESW	19	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
33	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315173	315173	FEE-62N102W #19NESW	NESW	19	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
34	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-08027	230365	315173	FEE #111X	NESW	19	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
35	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	315174	315174	FEE-62N102W #19NWSE	NWSE	19	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
36	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-08028	230366	315174	FEE #112X	NWSE	19	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					

37	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315175	315175	FEE-62N102W #19SESE	SESE	19	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
38	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08029	230367	315175	FEE #113X	SESE	19	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
39	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315176	315176	UNION PACIFIC-62N102W #20SESW	SESW	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
40	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08030	230368	315176	UNION PACIFIC #104X-20	SESW	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
41	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315177	315177	FEE-62N102W #29SWNW	SWNW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
42	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08031	230369	315177	FEE #114X	SWNW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
43	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315178	315178	FEE-62N102W #30SENE	SENE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
44	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08032	230370	315178	FEE #107X	SENE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
45	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315179	315179	ASSOCIATED-62N103W #24NWSE	NWSE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
46	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	WELL	103-08034	230372	315179	ASSOCIATED #A-5X	NWSE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
47	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315180	315180	GRAY-62N103W #24NESE	NESE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
48	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08035	230373	315180	GRAY #A-20X	NESE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
49	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315184	315184	EMERALD-62N103W #25NWSE	NWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
50	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08041	230379	315184	EMERALD #63X	NWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
51	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315185	315185	NEAL-62N103W #25NWNE	NWNE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
52	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08042	230380	315185	NEAL #7X	NWNE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
53	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315186	315186	NEAL-62N103W #25SENW	SENW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
54	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08043	230381	315186	NEAL #8X	SENW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
55	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315188	315188	EMERALD-62N102W #30NWNW	NWNW	30	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
56	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08046	230384	315188	EMERALD #71X	NWNW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
57	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315189	315189	RIGBY-62N103W #24SWSE	SWSE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
58	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08047	230385	315189	RIGBY #5X	SWSE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
59	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315203	315203	EMERALD-62N103W #25SENE	SENE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
60	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08072	230409	315203	EMERALD #70X	SENE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
61	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315224	315224	EMERALD-62N102W #30SWNW	SWNW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
62	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08104	230441	315224	EMERALD #72X	SWNW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
63	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315225	315225	EMERALD-62N102W #30NESW	NESW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
64	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08105	230442	315225	EMERALD #73X	NESW	30	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
65	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315253	315253	EMERALD-62N103W #26SWNE	SWNE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
66	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08169	230502	315253	EMERALD #74X	SWNE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
67	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315254	315254	AC MCLAUGHLIN- 62N103W #14NENW	NENW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
68	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08170	230503	315254	AC MCLAUGHLIN #67X	NENW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
69	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315316	315316	MCLAUGHLIN A. C.- 62N103W #23NWNW	NWNW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
70	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08292	230624	315316	MCLAUGHLIN A. C. # #68X	NWNW	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
71	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315317	315317	LN HAGOOD-62N103W #23NWNE	NWNE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
72	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08293	230625	315317	LN HAGOOD #A-15X	NWNE	23	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
73	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315318	315318	MCLAUGHLIN, A C- 62N103W #14SWSE	SWSE	14	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
74	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08294	230626	315318	MCLAUGHLIN, A C #69X	SWSE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
75	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315321	315321	A.C. MCLAUGHLIN-62N103W #13SESE	SESE	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
76	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08297	230629	315321	A.C. MCLAUGHLIN #71X	SESE	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
77	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315322	315322	MCLAUGHLIN A.C. - 62N103W #13SESW	SESW	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
78	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08298	230630	315322	MCLAUGHLIN A.C. # #75X	SESW	13	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
79	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315323	315323	FEE-62N102W #19NENW	NENW	19	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
80	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08299	230631	315323	FEE #116X	NENW	19	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
81	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315324	315324	HAGOOD L N-62N103W #14SESE	SESE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
82	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08300	230632	315324	HAGOOD L N #A-16X	SESE	14	2N	103W

	<u>County</u>		<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO		FEDERAL	16700	CHEVRON USA INC				
83	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315325	315325	MCLAUGHLIN, A C-62N103W #13SWSE	SWSE	13	2N	103W
	<u>County</u>		<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
84	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08301	230633	315325	MCLAUGHLIN, A C #70X	SWSE	13	2N	103W
	<u>County</u>		<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO		FEDERAL	16700	CHEVRON USA INC				
85	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315326	315326	GRAY-62N103W #13SESE	SESE	13	2N	103W
	<u>County</u>		<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
86	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08302	230634	315326	GRAY #A-21X	SESE	13	2N	103W
	<u>County</u>		<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO		FEDERAL	16700	CHEVRON USA INC				
87	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315335	315335	GRAY-62N103W #24NENE	NENE	24	2N	103W
	<u>County</u>		<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
88	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08317	230649	315335	GRAY #A-22X	NENE	24	2N	103W
	<u>County</u>		<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO		FEDERAL	16700	CHEVRON USA INC				
89	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315336	315336	S B LACY-62N103W #24SWNW	SWNW	24	2N	103W
	<u>County</u>		<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
90	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08318	230650	315336	S B LACY #9X	SWNW	24	2N	103W
	<u>County</u>		<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO		FEE	16700	CHEVRON USA INC				
91	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315337	315337	A.C. MCLAUGHLIN-62N103W #24SWNE	SWNE	24	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
92	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08319	230651	315337	A.C. MCLAUGHLIN #73X	SWNE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
93	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315338	315338	MCLAUGHLIN, A C-62N103W #24NWNE	NWNE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
94	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08320	230652	315338	MCLAUGHLIN, A C #72X	NWNE	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
95	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315339	315339	MCLAUGHLIN, A C-62N103W #24NWNW	NWNW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
96	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08321	230653	315339	MCLAUGHLIN, A C #74X	NWNW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
97	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315395	315395	EMERALD-62N103W #36SEW	SEW	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
98	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08437	230768	315395	EMERALD #75X	SEW	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
99	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315396	315396	CHEVRON FEE-62N102W #31SEW	SEW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
100	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08438	230769	315396	CHEVRON FEE #117X	SEW	31	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
101	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315406	315406	UPRR-62N102W #32SWSW	SWSW	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
102	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08450	230781	315406	UPRR #106 X 32	SWSW	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
103	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315425	315425	EMERALD-62N103W #36SENE	SENE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
104	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08480	230811	315425	EMERALD #77X	SENE	36	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
105	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315426	315426	EMERALD-62N103W #25SWSW	SWSW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
106	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08481	230812	315426	EMERALD #76X	SWSW	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
107	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315435	315435	EMERALD-62N103W #26NESE	NESE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
108	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08491	230822	315435	EMERALD #78X	NESE	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
109	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315436	315436	EMERALD-62N103W #26NENW	NENW	26	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
110	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08492	230823	315436	EMERALD #82X	NENW	26	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
111	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315437	315437	UNION PACIFIC-62N102W #21NESW	NESW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
112	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08495	230826	315437	UNION PACIFIC #108X-21	NESW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
113	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315438	315438	UNION PACIFIC-62N102W #32SWSE	SWSE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
114	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08497	230828	315438	UNION PACIFIC #109 X 32	SWSE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
115	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315439	315439	UNION PACIFIC-62N102W #32SESE	SESE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
116	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08498	230829	315439	UNION PACIFIC #107 X 32	SESE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
117	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315454	315454	UNION PACIFIC-62N102W #29SENW	SENW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
118	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08522	230853	315454	UNION PACIFIC #111X-29	SENW	29	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
119	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315459	315459	UNION PACIFIC-62N102W #21NESW	NESW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
120	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08530	230861	315459	UNION PACIFIC #110X-21	NESW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
121	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315463	315463	COLTHARP-62N102W #35SWSE	SWSE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
122	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08535	230866	315463	COLTHARP #9X	SWSE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
123	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315464	315464	OLDLAND-62N102W #36SWSE	SWSE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
124	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08536	230867	315464	OLDLAND #5X	SWSE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
125	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315475	315475	COBB-STRINGER-HEFLEY-61N102W #2SWNW	SWNW	2	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
126	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08562	230893	315475	COBB-STRINGER-HEFLEY #4X	SWNW	2	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
127	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	315476	315476	CARNEY-61N102W #4NWNE	NWNE	4	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
128	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08563	230894	315476	CARNEY #37 X 4	NWNE	4	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
129	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315480	315480	CHEVRON FEE-62N102W #17SESW	SESW	17	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
130	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08575	230906	315480	CHEVRON FEE #121X	SESW	17	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
131	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315500	315500	UNION PACIFIC-62N102W #22SWNW	SWNW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
132	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08606	230937	315500	UNION PACIFIC #113X22	SWNW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
133	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315502	315502	FEE-62N102W #22NWSW	NWSW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
134	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08612	230943	315502	FEE #53AX	NWSW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
135	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315512	315512	A. C. MCLAUGHLIN- 61N102W #4SWNW	SWNW	4	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
136	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	WELL	103-08630	230961	315512	A. C. MCLAUGHLIN #A-3X	SWNW	4	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
137	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315530	315530	FEE-62N102W #19NENE	NENE	19	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
138	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08663	230994	315530	FEE #122X	NENE	19	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
139	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315531	315531	CHEVRON FEE-62N102W #21NWSW	NWSW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
140	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08664	230995	315531	CHEVRON FEE #124X	NWSW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
141	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315533	315533	UNION PACIFIC-62N102W #21NWNW	NWNW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
142	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08666	230997	315533	UNION PACIFIC #115 X 21	NWNW	21	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
143	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315534	315534	U P R R-62N102W #22SENW	SENW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
144	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08667	230998	315534	U P R R #117 X 22	SENW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
145	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	315537	315537	RECTOR-61N102W #3SWNE	SWNE	3	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
146	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08672	231003	315537	RECTOR #11X	SWNE	3	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
147	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315542	315542	CHEVRON FEE-62N102W #20SWNW	SWNW	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
148	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08681	231012	315542	CHEVRON FEE #125X	SWNW	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
149	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	315544	315544	LEVISON-62N102W #26NWNE	NWNE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
150	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08683	231014	315544	LEVISON #35X	NWNE	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				

Incidents Proposed for Transfer Summary

< No row provided >

Related Wells & Facilities Not Proposed for Transfer Summary

< No row provided >

Related Incidents Not Proposed for Transfer Summary

< No row provided >

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
1311266	CORRESPONDENCE
1311267	CORRESPONDENCE
402847282	Form 09 SUBMITTED
402847483	EDD-I-WELLS-FACILITIES-PROPOSED
402867874	FORM 9 INTENT ATTESTATION

Total Attach: 5 Files

<u>COA Type</u>	<u>Description</u>
0 COA	

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Financial Assurance	Both operators have resolved all issues and accepted the COAs. Form 9 approved.	04/18/2023
Financial Assurance	<p>I am reviewed the transfer again with the following issues noted below.</p> <p>Chevron #40284700 to Scout #402887795</p> <ul style="list-style-type: none"> · Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation. · There are two Unaccounted For Facilities that need to be accounted for as follows: <ul style="list-style-type: none"> o Location ID #311804 Facility ID #444035 Spill or Release o Location ID #314367 Facility ID #314367 <p>If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.</p> <p>If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.</p> <ul style="list-style-type: none"> · There are 20 unaccounted for incidents related to this transfer. See Attached. <p>These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.</p> <ol style="list-style-type: none"> 1. If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list. 2. If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation. <p>If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.</p> <p>Chevron #402847248 to Scout #402890468</p> <ul style="list-style-type: none"> · Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation. · There is one Unaccounted For Facility (Location #314373, Facility # 480349) that needs to be accounted for. <p>If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.</p> <p>If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.</p> <ul style="list-style-type: none"> · There are 19 unaccounted for incidents related to this transfer. See Attached. <p>These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.</p> <p>If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.</p>	11/23/2022

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847259 to Scout #402890487

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847267 to Scout #402890493

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314622, Facility # 448608) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 18 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847273 to Scout #402890516

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314646, Facility # 453683) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 21 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847276 to Scout #402890528

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314763, Facility # 481149) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 40 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847277 to Scout #402891430

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are two Unaccounted For Facilities that need to be accounted for as follows:

- o Location ID #314933 Facility ID #438685 Spill or Release

o Location ID #314965 Facility ID #480932 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847282 to Scout #402891448

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #315324, Facility # 481858) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 29 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847287 to Scout #402891495

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #315740, Facility # 447266) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847293 to Scout #402891516

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #316136, Facility # 446036) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 28 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847295 to Scout #402891587

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847312 to Scout #402891604

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are 6 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847322 to Scout #402891631

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are 7 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847328 to Scout #402891662

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are five Unaccounted For Facilities that need to be accounted for as follows:

- o Location ID #413288 Facility ID #448925 Spill or Release

- o Location ID #413288 Facility ID #457749 Spill or Release

- o Location ID #426403 Facility ID #481872 Flowline System

o Location ID #426403 Facility ID #483023 Spill or Release

o Location ID #451320 Facility ID #451090 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 19 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847336 to Scout #402891690

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847928 to Scout #402891710

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847952 to Scout #402891752

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Assuming the other Form 9 requirements are met, all Form 9s shall now be passed with the following two COAs:

The Buying Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Buyer will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

The Selling Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Seller will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

Please note that each operator needs confirm that it will abide by the aforementioned COA by responding to this email. The correspondence will be uploaded to the form.

If the operators have submitted a Form 3, please provide the following comment when submitting the revised Form 3.

Form 3 Document # ____ is submitted as a result of an approved Form 9 Transfer of Operatorship and it replaces Form 3 document # ____.

Please reach out with any questions.

	<p>Thanks,</p> <p>Deb</p>	
Financial Assurance	<p>I have reviewed all 17 pairs of Intent and Subsequent documents involved in your transfer. I have noted below some issues that will need to be resolved before we can approve the transfer.</p> <p>Problem 1: For the following 15 Subsequent documents (402887795, 402890468, 402890487, 402890493, 402890516, 402890528, 402891430, 402891448, 402891495, 402891516, 402891587, 402891604, 402891631, 402891662 and 402891690), the Wells and Facilities Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.</p> <p>Solution 1: Please resubmit all 15 of the Wells and Facilities Transferred spreadsheets listing the current operator reflected in COGIS.</p> <p>Problem 2: For the last two Subsequent documents (402891710 and 402891752), the Incidents Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.</p> <p>Solution 2: Please resubmit both of the Incidents Transferred spreadsheets for subsequent document #402891710 and #402891751 listing the current operator reflected in COGIS.</p> <p>Problem 3: There are Related Wells and Facilities that are not accounted for in the transfer.</p> <p>Solution 3: I have attached a workbook that lists the Related Wells and Facilities that are not accounted for. In order for the transfer to be approved, the Related Wells and Facilities must be accounted for by one or a combination of the following options:</p> <p>Solution 3a: Add the well and location to the Wells and Facilities Transferred list in the Subsequent.</p> <p>Solution 3b: Generate and submit a Related Wells and Facilities – Not Transferred List. If not transferring the wells and facilities, the COGCC will also require a Seller Retains Responsibility Attestation. Guidance for this attestation can also be found in the attachment.</p> <p>Problem 4: In the same workbook as referenced in Problem 3, there is a list of Related Incidents that are not accounted for. Most of these incidents are Unresolved Field Inspections with Corrective Actions. These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or both of the following ways.</p> <p>Solution 4a: If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.</p> <p>Solution 4b: If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.</p> <p>If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.</p> <p>For both Problems 3 and 4 the lists include Unresolved Spill/Release. If the Spill/Release is closed, the COGCC does not require that the Spill/Release be transferred. It is up to the operators to determine whether or not they should be transferred. All revised and new documents can be emailed to me and I will upload them to Subsequent #402891752.</p> <p>Please reach out with any questions.</p>	04/01/2022
Total: 3 comment(s)		