

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402847322

Receive Date:

11/10/2021

TRANSFER OF OPERATORSHIP

A Selling Operator will notify the Commission about the transfer of any Transferable Item associated with its Oil and Gas Operations to a Buying Operator by filing a Form 9, Transfer of Operatorship – Intent, with the Commission at least 30 days, or as soon as practicable, before the anticipated transfer date. (Rule 218.b.) When a transaction subject to a Form 9 – Intent becomes final, the Buying Operator will submit a Form 9 – Subsequent within 7 days of closing. (Rule 218.d.(1).)

Type of Form 9, Transfer of Operatorship: ☒ **Intent** ☐ **Subsequent** Intent # _____

OPERATOR INFORMATION

SELLING OPERATOR INFORMATION

OGCC Operator Number: 16700 Contact Name and Telephone:
Name of Operator: CHEVRON USA INC Name: Jimmy Lozano
Address: 100 CHEVRON ROAD Phone: (432) 687-7696
City: RANGELY State: CO Zip: 81648 Email: jimmy.lozano@chevron.com

BUYING OPERATOR INFORMATION

OGCC Operator Number: 10779 Contact Name and Telephone:
Name of Operator: SCOUT ENERGY MANAGEMENT LLC Name: Tee Brown
Address: 13800 MONTFORT DRIVE SUITE 100 Phone: (972) 325-1027
City: DALLAS State: TX Zip: 75240 Email: tbrown@scoutep.com

TRANSFER INFO

Transfer Dates

Form 9 Intent - Anticipated Date of Transfer: 12/01/2021

Form 9 Subsequent - Effective Date of Transfer: _____ s

Confidentiality

Transfer is Confidential: No

Financial Assurance

Form 9 Intent - Estimated amount of Financial Assurance the Buying Operator will submit prior to anticipated date of transfer: \$ 100,000

Form 9 Subsequent - The Buying Operator's Financial Assurance:

SUBSEQUENT LIABILITY

Rule 218.d.(1).D.i.

"For Transferable Items listed in Rule 218.d.(1).B.i an acknowledgment that upon the effective date of transfer, that the Buying Operator assumes all responsibility for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.i. ☐

Rule 218.d.(1).D.ii.

"For Transferable Items listed in Rule 218.d.(1).B.ii or iii, an acknowledgment that the Buying Operator may be or may become responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders if the Buying Operator takes any action, or fails to take any action, that would cause such Transferable Item to be out of compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.ii. ☐

Rule 218.d.(1).D.iii.

"For Transferable Items not listed in Rule 218.d.(1).B.i-iii but Related in the Commission's records, an acknowledgment that the Commission will presume that the Transferable Item was transferred, and that the Buying Operator is responsible for compliance with the Act, the Commission's Rules, and all terms and conditions of existing Permits and Commission orders for the Transferable Items."

In checking this box the Buying Operator's acknowledges the subsequent liability pursuant to Rule 218.d.(1).D.iii. ☐

SUBMITTAL

OPERATOR COMMENT AND SUBMITTAL

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Julie Webb Email: julie.webb@chevron.com

Signature: Title: Sr. Regulatory Analyst Date: 11/10/2021

Wells & Facilities Proposed for Transfer Summary

1	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397179	397179	LEVISON-62N102W #22NWNW	SESE	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
2	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06172	229091	397179	UNION PACIFIC #64-22	NWNW	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
3	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06181	229099	397179	LEVISON #15	SESE	22	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
4	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397181	397181	LARSON, M B-62N102W #25NWNW	NWNW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
5	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06184	229102	397181	LARSON, M B #D7-25	NWNW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
6	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397182	397182	M B LARSON-62N102W #25SWNW	SWNW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
7	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06185	229103	397182	M B LARSON #D5-25	SWNW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
8	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397183	397183	M B LARSON-62N102W #25NESW	NESW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
9	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06189	229106	397183	M B LARSON #C4-25	NESW	25	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					

	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
10	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397184	397184	LARSON, M B-62N102W #25SENW	SENW	25	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
11	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06190	229107	397184	LARSON, M B #D-6-25	SENW	25	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
12	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397185	397185	NIKKEL-62N102W #25NWSE	NWSE	25	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
13	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06191	229108	397185	NIKKEL #A-2	NWSE	25	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
14	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397186	397186	NIKKEL-62N102W #25SESE	SESE	25	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
15	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06193	229110	397186	NIKKEL #A-1	SESE	25	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
16	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397187	397187	UNION PACIFIC-62N102W #27SENW	SENW	27	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
17	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06203	229120	397187	FEE #61	NWNW	27	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
18	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397188	397188	LEVISON-62N102W #27SENE	SENE	27	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					

	RIO BLANCO		16700	CHEVRON USA INC					
19	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06215	229132	397188	LEVISON #5	SENE	27	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
20	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397189	397189	LEVISON-62N102W #27NESE	NESE	27	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
21	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06216	229133	397189	LEVISON #3	NESE	27	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
22	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397190	397190	UNION PACIFIC-62N102W #28NWNW	NWNW	28	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
23	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06218	229135	397190	UNION PACIFIC #42-28	NWNW	28	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
24	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397191	397191	UNION PACIFIC-62N102W #29SENW	SENW	29	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
25	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06230	229146	397191	UNION PACIFIC #52-29	SENW	29	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
26	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397193	397193	UNION PACIFIC-62N102W #29NWSE	NWSE	29	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
27	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06232	229148	397193	UNION PACIFIC #37-29	NWSE	29	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					

	RIO BLANCO	FEE	16700	CHEVRON USA INC					
28	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397196	397196	EMERALD-62N102W #30NWNW	NWNW	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
29	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06237	229153	397196	EMERALD #31	NWNW	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
30	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397197	397197	EMERALD-62N102W #30NWSW	NWSW	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
31	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06239	229155	397197	EMERALD #33	NWSW	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
32	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397198	397198	EMERALD-62N102W #30SENV	SENV	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
33	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06241	229157	397198	EMERALD #7	SENV	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
34	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397199	397199	RAVEN-62N102W #30NWNE	NWNE	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO		16700	CHEVRON USA INC					
35	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06243	229159	397199	RAVEN #B-2	NWNE	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
36	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397200	397200	FEE-62N102W #30SENE	SENE	30	2N	102W
	County	Min.Owner. Type	Current Operator Num	Current Operator Name					

	RIO BLANCO		16700	CHEVRON USA INC					
37	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06246	229162	397200	FEE #16	SENE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
38	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	CENTRALIZED EP WASTE MGMT FAC	-	149001	397201	RANGELY LANDFARM #	SWSW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
39	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397201	397201	EMERALD-62N102W #31SWSW	SWSW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
40	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06252	229167	397201	EMERALD #43	SWSW	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
41	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397202	397202	FEE-62N102W #		31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
42	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06260	229175	397202	FEE #70		31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
43	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397204	397204	S H MCLAUGHLIN-62N102W #32SENE	SENE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
44	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06274	229189	397204	S H MCLAUGHLIN #4-32	SENE	32	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
45	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397208	397208	RECTOR-62N102W #34SESE	SESE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					

	RIO BLANCO			16700	CHEVRON USA INC				
46	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06292	229205	397208	RECTOR #5	SESE	34	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
47	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397209	397209	RECTOR-62N102W #35SWSW	SWSW	35	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
48	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06294	229207	397209	RECTOR #4	SWSW	35	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
49	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397210	397210	LARSON, F V "B" - 62N102W #36NENW	NENW	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
50	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06300	229212	397210	LARSON, F V "B" #7	NENW	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
51	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397211	397211	OLDLAND, E-62N102W #36SWSE	SWSE	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
52	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06304	229216	397211	OLDLAND, E #3	SWSE	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
53	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397212	397212	WALBRIDGE, L B- 62N102W #36SWSE	SWSE	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
54	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06308	229220	397212	WALBRIDGE, L B #3	SWSE	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				

	RIO BLANCO	FEE		16700	CHEVRON USA INC				
55	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397213	397213	WEYRAUCH "A"- 62N102W #36NENE	NENE	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
56	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06309	229221	397213	WEYRAUCH "A" #3-36	NENE	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
57	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397214	397214	LARSON, M B-62N102W #36SENE	SENE	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
58	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06310	229222	397214	LARSON, M B #D-1-36	SENE	36	2N	102W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
59	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397217	397217	A.C. MCLAUGHLIN- 62N103W #11SESE	SESE	11	2N	103W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
60	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06318	282802	397217	A.C. MCLAUGHLIN #25	SESE	11	2N	103W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
61	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397218	397218	A. C. MCLAUGHLIN- 62N103W #14NWNW	NWNW	14	2N	103W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO			16700	CHEVRON USA INC				
62	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	WELL	103-06319	229228	397218	A. C. MCLAUGHLIN #45	NWNW	14	2N	103W
	County	Min.Owner. Type		Current Operator Num	Current Operator Name				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
63	Facility Type	API	Facility ID	Location ID	Facility Name	QtrQtr	Sec	Twp	Rng
	LOCATION	-	397219	397219	LARSON, M B-62N103W #15SESW	SESW	15	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
64	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-06329	229238	397219	LARSON, M B #A-1	SESW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
65	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397350	397350	FEDERAL-61N103W #15SWSW	SWSW	15	1N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
66	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07090	229435	397350	FEDERAL #1 (14-15)	SWSW	15	1N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
67	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397376	397376	OLDLAND, E-62N102W #36SESE	SESE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
68	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07152	229496	397376	OLDLAND, E #4	SESE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
69	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397403	397403	GOV 23-26-62N102W #26NESW	NESW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
70	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07197	229541	397403	GOV 23-26 #2M	NESW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
71	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397412	397412	CHEVRON ET AL GOV D- 03267-62N102W #34SWNE	SWNE	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
72	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07208	229551	397412	CHEVRON ET AL GOV D- 03267 #1-M	SWNE	34	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
73	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397434	397434	CHEVRON ET AL- EMERALD-62N102W #30SENW	SENW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
74	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07247	229590	397434	CHEVRON ET AL- EMERALD #3M	SENW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
75	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397441	397441	DOUGLAS PASS UNIT- 61S101W #10NWSE	NWSE	10	1S	101W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
76	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07261	229604	397441	DOUGLAS PASS UNIT #1 (33-10)	NWSE	10	1S	101W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
77	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397471	397471	FEDERAL-62N103W #14SWSW	SWSW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
78	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07317	229660	397471	FEDERAL #5M-14-14	SWSW	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
79	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397475	397475	RMU FED-62N102W #35NESE	NESE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
80	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07330	229673	397475	RMU FED #4M	NESE	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
81	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	397493	397493	FEE-62N102W #27NWNE	NWNE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
82	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07360	229703	397493	FEE #77X	NWNE	27	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
83	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397494	397494	FEE-62N102W #30SESE	SESE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
84	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07363	229706	397494	FEE #1-D	SESE	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
85	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397543	397543	C T CARNEY-62N102W #35NWNW	NWNW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
86	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07450	229793	397543	C T CARNEY #26X-35	NWNW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
87	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397603	397603	UNION PACIFIC-62N102W #34SWNW	SWNW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
88	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07596	229937	397603	UNION PACIFIC #95X-34	SWNW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
89	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07604	229945	397604	CARNEY C T #31X-4	NWNW	4	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
90	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397605	397605	SHARPLES-MCLAUGHLIN-62N102W #33SWNW	SWNW	33	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
91	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07605	229946	397605	SHARPLES-MCLAUGHLIN #11 X 33	SWNW	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
92	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397650	397650	A C MCLAUGHLIN- 62N103W #14NWSE	NWSE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
93	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07691	230032	397650	A C MCLAUGHLIN #59X	NWSE	14	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
94	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397677	397677	M B LARSON-62N103W #15SESW	SESW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
95	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07737	230078	397677	M B LARSON #A-4X	SESW	15	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
96	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397714	397714	EMERALD-62N103W #25NWSE	NWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
97	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07810	230151	397714	EMERALD #63X	NWSE	25	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
98	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397719	397719	S B LACY-62N103W #24SWNW	SWNW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
99	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-07828	230169	397719	S B LACY #5X	SWNW	24	2N	103W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
100	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397956	397956	FEE-62N102W #29SENE	SENE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
101	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08439	230770	397956	FEE #118X	SENE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
102	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397969	397969	CHEVRON-62N102W #31SWSE	SWSE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
103	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08493	230824	397969	CHEVRON #120X	SWSE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
104	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	397970	397970	FEE-62N102W #29NENE	NENE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
105	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08494	230825	397970	FEE #119X	NENE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
106	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398048	398048	LEVISON-62N102W #23SWSW	SWSW	23	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
107	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08684	231015	398048	LEVISON #36X	SWSW	23	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
108	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398053	398053	UNION PACIFIC-62N102W #21SESW	SESW	16	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
109	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08705	231036	398053	UNION PACIFIC #121X21	SESW	16	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
110	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398057	398057	CHEVRON FEDERAL-61S100W #2SESW	SESW	2	1S	100W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
111	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08711	231042	398057	CHEVRON FEDERAL #2-1-100-1	SESW	2	1S	100W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
112	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398085	398085	CHEVRON FEDERAL-62N102W #28NESE	NESE	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
113	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08767	231098	398085	CHEVRON FEDERAL #134-X	NESE	28	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
114	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398107	398107	ASSOCIATED-61N102W #4SENE	SENE	4	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
115	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-08812	231143	398107	ASSOCIATED #B-4X	SENE	4	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
116	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398263	398263	AMOCO LARSON-62N102W #36SWNW	SWNW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
117	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	PIT	-	445127	398263	COLLECTION STATION 39 #	SWNW	36	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
118	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398284	398284	CARNEY-62N102W #35SEW	SEW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
119	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09117	231447	398284	CARNEY #40X35	SEW	35	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
120	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398292	398292	LACY S. B.-62N103W #24SWSW	SWSW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
121	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09143	231473	398292	LACY S. B. # #10Y	SWSW	24	2N	103W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
122	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398294	398294	C.T.CARNEY-62N102W #34SEW	SEW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
123	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09154	231484	398294	C.T.CARNEY #42Y34	SEW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
124	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398304	398304	UNION PACIFIC-62N102W #31SESE	SESE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
125	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09179	231509	398304	UNION PACIFIC #63AX-31	SESE	31	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
126	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398322	398322	EMERALD-62N102W #30SWSW	SWSW	30	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
127	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09234	231563	398322	EMERALD #3AX	SWSW	30	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
128	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398339	398339	F V LARSON B-62N102W #36NWNW	NWNW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
129	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09266	231595	398339	F V LARSON B #26Y	NWNW	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
130	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398342	398342	UNION PACIFIC-62N102W #20NWSW	NWSW	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
131	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09272	231601	398342	UNION PACIFIC #144Y20	NWSW	20	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
132	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398343	398343	CHEVRON FEE-62N102W #29NWSW	NWSW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
133	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09273	231602	398343	CHEVRON FEE #148Y	NWSW	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
134	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398344	398344	LEVISON-62N102W #26SWSW	SWSW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
135	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09274	231603	398344	LEVISON #36Y	SWSW	26	2N	102W

	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
136	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398358	398358	RANGELY-62N102W #33NENE	NENE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
137	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09334	231663	398358	RANGELY #1M-41-33B	NENE	33	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
138	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398370	398370	CHEVRON FEE-62N102W #19NWSE	NWSE	19	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
139	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09398	231727	398370	CHEVRON FEE #2M-33- 19B	NWSE	19	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
140	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398387	398387	L B WALBRIDGE-61N102W #1NENW	NENW	1	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
141	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09483	231812	398387	L B WALBRIDGE #5Y	NENW	1	1N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEE	16700	CHEVRON USA INC					
142	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398389	398389	LARSON*M B "D";- 62N102W #36NESE	NESE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO		16700	CHEVRON USA INC					
143	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09489	231818	398389	LARSON*M B "D"; #2X36	NESE	36	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>	<u>Current Operator Num</u>	<u>Current Operator Name</u>					
	RIO BLANCO	FEDERAL	16700	CHEVRON USA INC					
144	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>

	LOCATION	-	398553	398553	TEXACO-CHEVRON FEE-62N102W #29SWSE	SWSE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
145	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09818	232147	398553	TEXACO-CHEVRON FEE #29-1	SWSE	29	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEE		16700	CHEVRON USA INC				
146	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398556	398556	TEXACO-AMOCO C.T.CARNEY-62N102W #34NENW	NENW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
147	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09823	232152	398556	TEXACO-AMOCO C.T.CARNEY #34-1	NENW	34	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				
148	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	LOCATION	-	398558	398558	TEXACO-LEVISON FEDERAL-62N102W #26SWSW	SWSW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO			16700	CHEVRON USA INC				
149	<u>Facility Type</u>	<u>API</u>	<u>Facility ID</u>	<u>Location ID</u>	<u>Facility Name</u>	<u>QtrQtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>
	WELL	103-09825	232154	398558	TEXACO-LEVISON FEDERAL #26-1	SWSW	26	2N	102W
	<u>County</u>	<u>Min.Owner. Type</u>		<u>Current Operator Num</u>	<u>Current Operator Name</u>				
	RIO BLANCO	FEDERAL		16700	CHEVRON USA INC				

Incidents Proposed for Transfer Summary

< No row provided >

Related Wells & Facilities Not Proposed for Transfer Summary

< No row provided >

Related Incidents Not Proposed for Transfer Summary

< No row provided >

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
1311277	CORRESPONDENCE
1311278	CORRESPONDENCE
402847322	Form 09 SUBMITTED
402847373	EDD-I-WELLS-FACILITIES-PROPOSED
402868018	FORM 9 INTENT ATTESTATION

Total Attach: 5 Files

<u>COA Type</u>	<u>Description</u>
0 COA	

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Financial Assurance	Both operators have resolved all issues and accepted the COAs. Form 9 approved.	04/19/2023
Financial Assurance	<p>I am reviewed the transfer again with the following issues noted below.</p> <p>Chevron #40284700 to Scout #402887795</p> <ul style="list-style-type: none"> · Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation. · There are two Unaccounted For Facilities that need to be accounted for as follows: <ul style="list-style-type: none"> o Location ID #311804 Facility ID #444035 Spill or Release o Location ID #314367 Facility ID #314367 <p>If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.</p> <p>If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.</p> <ul style="list-style-type: none"> · There are 20 unaccounted for incidents related to this transfer. See Attached. <p>These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.</p> <ol style="list-style-type: none"> 1. If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list. 2. If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation. <p>If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.</p> <p>Chevron #402847248 to Scout #402890468</p> <ul style="list-style-type: none"> · Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation. · There is one Unaccounted For Facility (Location #314373, Facility # 480349) that needs to be accounted for. <p>If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.</p> <p>If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.</p> <ul style="list-style-type: none"> · There are 19 unaccounted for incidents related to this transfer. See Attached. <p>These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.</p> <p>If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.</p>	11/23/2022

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847259 to Scout #402890487

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847267 to Scout #402890493

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314622, Facility # 448608) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 18 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847273 to Scout #402890516

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314646, Facility # 453683) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 21 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847276 to Scout #402890528

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #314763, Facility # 481149) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 40 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847277 to Scout #402891430

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are two Unaccounted For Facilities that need to be accounted for as follows:

- o Location ID #314933 Facility ID #438685 Spill or Release

o Location ID #314965 Facility ID #480932 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847282 to Scout #402891448

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #315324, Facility # 481858) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 29 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847287 to Scout #402891495

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #315740, Facility # 447266) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 25 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847293 to Scout #402891516

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There is one Unaccounted For Facility (Location #316136, Facility # 446036) that needs to be accounted for.

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

- There are 28 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847295 to Scout #402891587

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are 26 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847312 to Scout #402891604

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are 6 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847322 to Scout #402891631

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are 7 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847328 to Scout #402891662

- Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

- There are five Unaccounted For Facilities that need to be accounted for as follows:

- o Location ID #413288 Facility ID #448925 Spill or Release

- o Location ID #413288 Facility ID #457749 Spill or Release

- o Location ID #426403 Facility ID #481872 Flowline System

o Location ID #426403 Facility ID #483023 Spill or Release

o Location ID #451320 Facility ID #451090 Spill or Release

If these facilities are to be transferred to Scout, then please add these facilities to the Wells and Facilities Transferred list.

If these facilities are to be retained by Chevron, then the facilities need to be added to a Wells Facilities – Not Transferred list. In addition to the list, a Seller retains responsibility Attestation must be submitted.

· There are 19 unaccounted for incidents related to this transfer. See Attached.

These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or more of the following ways.

If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.

If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.

If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.

Chevron #402847336 to Scout #402891690

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847928 to Scout #402891710

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Chevron #402847952 to Scout #402891752

· Buyer Notified Local Govt. Attestation – Please specify the individual contacted at Rio Blanco County and resubmit the attestation.

Assuming the other Form 9 requirements are met, all Form 9s shall now be passed with the following two COAs:

The Buying Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Buyer will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

The Selling Operator must file a Form 3, Financial Assurance Plan within 10 business days of Form 9 approval. Per Rule 702, Seller will then provide any required additional financial assurance as soon as practicable but no later than 90 days from the Commission's approval of the Form 3, Financial Assurance Plan.

Please note that each operator needs confirm that it will abide by the aforementioned COA by responding to this email. The correspondence will be uploaded to the form.

If the operators have submitted a Form 3, please provide the following comment when submitting the revised Form 3.

Form 3 Document # ____ is submitted as a result of an approved Form 9 Transfer of Operatorship and it replaces Form 3 document # ____.

Please reach out with any questions.

	<p>Thanks,</p> <p>Deb</p>	
Financial Assurance	<p>I have reviewed all 17 pairs of Intent and Subsequent documents involved in your transfer. I have noted below some issues that will need to be resolved before we can approve the transfer.</p> <p>Problem 1: For the following 15 Subsequent documents (402887795, 402890468, 402890487, 402890493, 402890516, 402890528, 402891430, 402891448, 402891495, 402891516, 402891587, 402891604, 402891631, 402891662 and 402891690), the Wells and Facilities Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.</p> <p>Solution 1: Please resubmit all 15 of the Wells and Facilities Transferred spreadsheets listing the current operator reflected in COGIS.</p> <p>Problem 2: For the last two Subsequent documents (402891710 and 402891752), the Incidents Transferred spreadsheets listed the current operator as Scout Energy Management LLC. This is incorrect since the transfer has not been approved.</p> <p>Solution 2: Please resubmit both of the Incidents Transferred spreadsheets for subsequent document #402891710 and #402891751 listing the current operator reflected in COGIS.</p> <p>Problem 3: There are Related Wells and Facilities that are not accounted for in the transfer.</p> <p>Solution 3: I have attached a workbook that lists the Related Wells and Facilities that are not accounted for. In order for the transfer to be approved, the Related Wells and Facilities must be accounted for by one or a combination of the following options:</p> <p>Solution 3a: Add the well and location to the Wells and Facilities Transferred list in the Subsequent.</p> <p>Solution 3b: Generate and submit a Related Wells and Facilities – Not Transferred List. If not transferring the wells and facilities, the COGCC will also require a Seller Retains Responsibility Attestation. Guidance for this attestation can also be found in the attachment.</p> <p>Problem 4: In the same workbook as referenced in Problem 3, there is a list of Related Incidents that are not accounted for. Most of these incidents are Unresolved Field Inspections with Corrective Actions. These corrective actions may or may not have been resolved. FIRs with outstanding corrective actions are transferable items that must be accounted for in the Form 9 in one or both of the following ways.</p> <p>Solution 4a: If the compliance responsibility for such an FIR transfers to the buyer include that FIR on a Related Incidents Transferred list.</p> <p>Solution 4b: If the compliance responsibility for such an FIR is retained by the seller include that FIR on a Related Incidents Not Transferred list and provide a Seller Retains Responsibility Attestation.</p> <p>If the parties perform the research and determine that all corrective actions for a particular FIR have been resolved, that FIR does not need to be listed on the Form 9 but will be subject to Rule 218.d(1)D.iii.</p> <p>For both Problems 3 and 4 the lists include Unresolved Spill/Release. If the Spill/Release is closed, the COGCC does not require that the Spill/Release be transferred. It is up to the operators to determine whether or not they should be transferred. All revised and new documents can be emailed to me and I will upload them to Subsequent #402891752.</p> <p>Please reach out with any questions.</p>	04/01/2022
Total: 3 comment(s)		