

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403382365

Date Received:
04/24/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10177
Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION
Address: 950 17TH STREET #2200
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
		reed.wold@state.co.us
		jeverhart@enerplus.com
		SGibbs@enerplus.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504490
Inspection Date: 01/17/2023 FIR Submit Date: 01/24/2023 FIR Status:

Inspected Operator Information:

Company Name: ENERPLUS RESOURCES (USA) CORPORATION Company Number: 10177
Address: 950 17TH STREET #2200
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 450827

Location Name: IRISH PAD Number: N/A County:
Qtrqr: SWSE Sec: 26 Twp: 8N Range: 67W Meridian: 6
Latitude: 40.626117 Longitude: -104.858296

FACILITY - API Number: 05-123-00 Facility ID: 450827

Facility Name: IRISH PAD Number: N/A
Qtrqr: SWSE Sec: 26 Twp: 8N Range: 67W Meridian: 6
Latitude: 40.626117 Longitude: -104.858296

CORRECTIVE ACTIONS:

1 CA# 167143

Corrective Action: Comply with Rule 606 to remove weed debris.
The corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

Date: 01/17/2023

Response: CA COMPLETED Date of Completion: 04/01/2023

weeds and debris removed 1-2 after inspection findings

Operator Comment: _____

COGCC Decision: _____

COGCC Representative: _____

2 CA# 167144

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Comply with Rule 1002.c. to prohibit vehicle traffic on the topsoil stockpile.

The corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

Date: 01/17/2023

Response: CA COMPLETED Date of Completion: 04/01/2023

Operator Comment: Reseeding performed on 4/1/23 to establish long term soil protection and stabilization

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jacob Everhart Signed: _____

Title: Regulatory Advisor Date: 4/24/2023 1:35:38 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files