

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403382375

Date Received:

04/24/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10177

Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

reed.wold@state.co.us

jeverhart@enerplus.com

SGibbs@enerplus.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504486

Inspection Date: 01/17/2023

FIR Submit Date: 01/23/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ENERPLUS RESOURCES (USA) CORPORATION

Company Number: 10177

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449968

Location Name: Colorado Lakes Number: Pad County: \_\_\_\_\_

Qtrqr: SWS Sec: 28 Twp: 8N Range: 67W Meridian: 6  
W

Latitude: 40.628235 Longitude: -104.904830

FACILITY - API Number: 05-123- -00 Facility ID: 449968

Facility Name: Colorado Lakes Number: Pad

Qtrqr: SWS Sec: 28 Twp: 8N Range: 67W Meridian: 6  
W

Latitude: 40.628235 Longitude: -104.904830

CORRECTIVE ACTIONS:

1 ☒ CA# 167121

Corrective Action: Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date: 01/17/2023

The corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 04/01/2023

Operator Comment: weed debris cleaned up within 1-2 days of inspection findings

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 ☒ CA# 167122

Corrective Action: Comply with Rule 1003. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. The corrective date is the date the location was observed out of compliance. Operator shall complete the corrective action as soon as environmental conditions will permit.

Date: 01/17/2023

Response: CA COMPLETED

Date of Completion: 04/01/2023

Operator Comment: Reseeding performed on 4/1/23 to establish long term soil protection and stabilization

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jacob Everhart

Signed: \_\_\_\_\_

Title: Regulatory Advisor

Date: 4/24/2023 1:39:07 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403382375	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files