

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2023

Submitted Date:

04/28/2023

Document Number:

708200192

## FIELD INSPECTION FORM

 Loc ID 317374 Inspector Name: Edwardson, Dylan On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 81490  
 Name of Operator: ST CROIX OPERATING INC  
 Address: P O BOX 13799  
 City: DENVER State: CO Zip: 80201
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Melnychenko, Paul	(303) 489-9298	stcroixexp@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272970	WELL	PA	05/05/2021	GW	121-10753	HICKERT 41C-18349	RI
317374	LOCATION	CL			-	Hickert 41C-18349	RI

**General Comment:**

This is a Final Reclamation Inspection for PA Well API#121-10753 and its associated tank battery. Well was plugged and abandoned 05/05/2021.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

DEBRIS

Comment: Cattle panels not installed and left on location. Refer to atached inspection photos.

Corrective Action: Comply with Rule 606 and remove debris from location.

Date: 05/06/2023

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type

Comment: All equipment has not been removed from the location as fencing was observed around the former skim pit and tank battery. Form 4 Sundry Notice (Doc #403094036) Operator's reclamation comment states that fencing was left standing to exclude livestock grazing. If the location is going to be fenced to exclude livestock grazing, then the entire reclamation area should be fenced to help establish vegetation. Fencing identified in this inspection will need to be removed.

Corrective Action: Comply with reclamation rules to remove all equipment (regardless of ownership) within three months of plugging (05/05/2021) the associated facility. All work should have been completed by 08/05/2021. Corrective action date is being backdated to when all equipment should have been removed.

Date: 08/05/2021

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 272970 Type: WELL API Number: 121-10753 Status: PA Insp. Status: RI

Facility ID: 317374 Type: LOCATION API Number: - Status: CL Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Fail No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded Fail Contoured Fail Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control Fail

Non cropland: Revegetated 80% Fail Cropland: perennial forage \_\_\_\_\_

Weeds present Fail Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment: This location does not comply with Rule 1004. It was observed during this inspection that the access/lease road has not been reclaimed, equipment/debris remains on location, and the reclamation areas have not revegetated with desirable perennial vegetation as exposed/bare soil was evident throughout. Additionally, undesirable vegetation (e.g. kochia and russian thistle) has established and does not appear to have been managed during the past growing season. Refer to attached inspection photos for documentation.

Corrective Action:	<p>Comply with Rule 1004. Reclaim access road, remove debris, and reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management. Corrective action date is the date the location was observed out of compliance.</p>	Date <b>04/20/2023</b>
<p>Overall Final Reclamation <b>Fail</b>      Well Release on Active Location <input type="checkbox"/>      Multi-Well Location <input type="checkbox"/></p>		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200211	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6097717">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6097717</a>