

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2023

Submitted Date:

05/02/2023

Document Number:

702501238

**FIELD INSPECTION FORM**

Loc ID 314609 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 760 HORIZON DRIVE STE 401  
City: GRAND JUNCTION State: CO Zip: 81506

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Johnson, Mike		Mike.Johnson@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229123	WELL	SI	12/01/2021	OW	103-06206	UNION PACIFIC 16-27	SI

**General Comment:**

[COGCC Inspection Report Summary](#)

On Tuesday, 05/02/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Management LLC on the Union Pacific 16-27 well, Location #314609, in Rio Blanco County, Colorado. This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority/NSO/Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable. Follow up inspection in response to FIRRs #403360604 & #403369220 submitted by Operator for Corrective Actions from Inspection #702500948 on 3/6/23.

While there during normal production operations the following compliance issue was observed:

1. Insufficient Stormwater BMPs for location and access road. Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	(970) 675-3700 / 911		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

				corrective date
Type: Submersible Pump	# 1			
Comment:				
Corrective Action:		Date:		
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:	Accessible with valve. Gauge installed.			
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 229123 Type: WELL API Number: 103-06206 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last Production - November 2021

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Ditches				
Berms	Fail					

Comment: Stormwater BMPs need implementation and maintenance. Insufficient BMPs to control vehicle tracking.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 06/02/2023

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501240	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102147">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102147</a>