

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/25/2023

Submitted Date:

04/25/2023

Document Number:

690204141

**FIELD INSPECTION FORM**

Loc ID: 333537 Inspector Name: COSTA, RYAN On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Logos		regulatory@logosresourcesllc.com	
SIMCOE		sjninspections@ikavenergy.co	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214199	WELL	PR	05/19/2010	GW	067-05521	BONDAD 33-9 10	RI
215423	WELL	PR	11/11/2015	CBM	067-07028	PETER PHILLIPS A 1	RI

**General Comment:**

On 4/18/2023, Ryan Costa conducted a stormwater management inspection. Inspection was not performed at wellsite due to locked gate. See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous corrective action was not reinspected due to locked gate. There is vehicle rutting along the access road up to the gate that needs to be repaired and stabilized.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 05/05/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403384511	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093806">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093806</a>
690204142	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093804">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093804</a>