

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2023

Submitted Date:

04/28/2023

Document Number:

702501215

FIELD INSPECTION FORM

Loc ID 315095 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 760 HORIZON DRIVE STE 400

City: GRAND JUNCTION State: CO Zip: 81506

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box
Bleil, Rob	970-290-2912	rbleil@utahgascorp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230246	WELL	PR	12/03/1976	GW	103-07905	FEDERAL 21-1	PR

General Comment:

[COGCC Inspection Report Summary](#)

On Thursday, 4/27/2023, Inspector Kirby Burchett, conducted a routine field inspection at Utah Gas Op LTD dba Utah Gas Corp on the Federal 21-1 well, Location #315095, in Rio Blanco County, Colorado. This location is within or in close proximity to a Parks & Wildlife (CPW) District with Black Bear/High Priority/NSO/Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal production operations the following compliance issue was observed:

- Stormwater BMPs need implementation and maintenance.
- Gas meter calibraton card not visibly displayed.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration card not visibly displayed. Located card inside meter box. Gas meter calibration card indicates the most recent calibration is within the past year.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.		Date: <u>05/12/2023</u>
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in containment		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Automation installed.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	30				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				
				Date:

Flaring:

Type				
Comment:				
Corrective Action:				
				Date:

Inspected Facilities

Facility ID: 230246 Type: WELL API Number: 103-07905 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater BMPs need implementation and maintenance. Insufficient BMPs to control vehicle tracking.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 05/29/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403388644	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6097789
702501219	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6097786