

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2023

Submitted Date:

05/02/2023

Document Number:

702501236

FIELD INSPECTION FORM

Loc ID: 314494 Inspector Name: Burchett, Kirby On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 6 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 16700
 Name of Operator: CHEVRON USA INC
 Address: 760 HORIZON DRIVE STE 401
 City: GRAND JUNCTION State: CO Zip: 81506

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Patterson, Chris		Chris.Patterson@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Johnson, Mike		Mike.Johnson@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228839	WELL	PR	12/01/2021	GW	103-05827	ASSOCIATED UNIT C 1	PR

General Comment:

[COGCC Inspection Report Summary](#)

On Tuesday, 05/02/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Scout Energy Management LLC on the Associated Unit C 1 well, Location #314494, in Rio Blanco County, Colorado. This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority/Density Habitats.

Any Corrective Actions from previous Inspections are still applicable. Follow up inspection in response to FIRR #403370654 submitted by Operator for Corrective Actions from Inspection #702501105 on 4/6/23.

While there during normal production operations the following compliance issue was observed:
 1. Blading of location and access roads does not address Stormwater BMPs needing to be implemented and maintained to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces. Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Ancillary equipment	# 2		
Comment:	Chemical tanks on plastic containment		
Corrective Action:		Date:	
Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	Accessible with valve		
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 228839 Type: WELL API Number: 103-05827 Status: PR Insp. Status: PR

Producing Well

Comment: [Submersible pump](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
				Material Handling And Spill Prevention		
Ditches						
		Ditches				
		Gravel				

Comment: Insufficient BMPs to control vehicle tracking.

Corrective Action: Provide proper Stormwater BMPs for vehicle tracking to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 05/19/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403391925	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102148
702501237	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102146