

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/03/2023

Submitted Date:

05/05/2023

Document Number:

690204180

FIELD INSPECTION FORM

Loc ID 321045 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
GEORGE KELLY		envexbaca@aol.com	
Levengood, John		jlevengood07@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205853	WELL	PR	05/01/2020	GW	009-06268	ROBBINS RANCH 'C' 1	RI
480585	TANK BATTERY	AC	08/26/2021		-	Robbins Ranch Tank	RI

General Comment:

On 5/3/2023, Ryan Costa conducted a follow up Location Inspection. See attached photos and additional details within this report.

The corrective actions of the previous inspections have not been completed. Operator is directed to perform corrective actions outlined on this inspection report immediately.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign does not reflect current Operator or emergency contact INFO. Previous corrective action not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/09/2022
Type	BATTERY		
Comment:	Sign does not reflect current Operator or emergency contact INFO. Sign not posted or information inaccurate at battery. Previous corrective action not completed.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	06/09/2022

Emergency Contact Number:

Comment:	The emergency contact number was not valid.		
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Tank is labeled NOT IN USE. All unused equipment needs to be removed. Previous corrective action not completed.		
Corrective Action:	Comply with Rule 606.	Date:	06/09/2022
Type	DEBRIS		
Comment:	There is weed debris around the equipment which needs to be removed. Previous corrective action not completed.		
Corrective Action:	Comply with Rule 606.	Date:	05/13/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>			
Other (Content)	<input type="text"/>			
Other (Capacity)	<input type="text"/>			
Other (Type)	<input type="text"/>			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	There is no secondary containment at the tank to contain a spill. The tank needs to be removed if not in use or the berm around the tank needs to be repaired. Previous corrective action not completed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	06/09/2022

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403395185	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6105466
690204181	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6105462