




00219539

H&R Well Services, Inc.  
0902 Rd 4  
Wiggins, Colorado  
80654



January 18, 1988



Mr. Paul Gagnon  
Kaurman & Wineberger  
Denver, Colorado

Re: Thayer #2-30  
NESW Sec 30-6N-67W

Dear Paul,

We performed the following work on your lease. This letter is also being forwarded to the Colorado Oil and Gas Commission at their request. It is needed in addition to the Form 4 when a well is plugged and abandoned.

Set CIBP at 6200' and dumped 4 sacks of cement.  
Cut pipe at the freepoint of 6061', and pulled casing to 2310'.  
Pumped 25 sacks of cement to 2310'.  
Lay casing down to the base of surface at 532', and spot 10 sacks.  
Spotted 10 sacks at surface.  
Cut the wellhead off 4' below ground level, and welded a plate.  
Backfilled the hole.

Sincerely,

*D. Rebol*  
Dave Rebol  
H&R Well Services, Inc.


Accept AS Form 4  
B

cc: Colorado Oil and Gas Conservation Commission

Well File



X



Mr. Paul ...  
1902 No. 4  
Winkler, ...  
1982



January 10, 1983

Mr. Paul ...  
1902 No. 4  
Winkler, ...

Mr. Paul ...  
1902 No. 4  
Winkler, ...

We performed the following work on your lease. This letter is also being forwarded to the Colorado Oil and Gas Commission at their request. It is needed in addition to the form when a well is plugged and abandoned.

5/15/80  
Jim I have talked to  
Dean Cummings with  
Sunset twice about  
Walter Properties getting  
a bond and submitting  
Form 10's. He assures me  
it will be taken care of.  
Please watch for the bond  
Bill

cc: Colorado Oil and Gas Conservation Commission