

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET

DENVER, COLORADO 80203



WILLIAM R. SMITH
Director

(303) 866-3531

RICHARD D. LAMM
Governor

FRANK J. PIRO
Deputy Director

February 13, 1986

Norm Walter Properties Inc.,
6395 Gunpark Drive/Penthouse
Boulder, Colorado 80301

*90 La Cantara Racquet Club
3737 Montgomery Dr.
Santa Rosa, Ca.*

RE: #1 Jones
SE NW 17-4N-69W

95405

Gentlemen:

707-544-9494

On February 3, 1983 we received a "Wellsite Geologists Report" on the subject well and on February 10, 1983 we received a completion report which was not on our OGCC Form 5. Since that time we have written several times for a Form 5 and status report, but to date we have had no response.

Rule 306 of the rules and regulations of the Commission provide that within thirty (30) days after the completion of any well, the owner or operator shall transmit to the Director the well completion or recompletion report and log (OGCC Form 5). Rule 305 provides that notice must be given to the Director when an operator expects to recomplete a well, abandon a well or change plans. On OGCC Form 4, we need a final P & A and cement verification. Further, Section 34-60-121 of the Colorado Revised Statutes states that any person who violates any rule of the Commission shall be subject to a penalty of not more than one thousand dollars (\$1,000.00) for each violation and for each day that such violation continues.

I am not interested in seeking a penalty, but merely bringing your well file up-to-date; however, if I have received no response from you within fifteen (15) days following receipt of this letter, I intend to take the matter to the Commission.

Walter Properties
February 13, 1986
Page 2

If you have any questions regarding this matter, please do not
hesitate to contact me.

Very truly yours,

William R. Smith

William R. Smith, P.E.
Director

WRS:bm

cc: Shepler & Thomas, Inc.