

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2023

Submitted Date:

06/01/2023

Document Number:

708200284

FIELD INSPECTION FORM

Loc ID 430313 Inspector Name: Edwardson, Dylan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10773
Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC
Address: 5251 DTC PKWY STE 950
City: GREENWOOD State: CO Zip: 80111

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
TRUITT, J CODY	281-513-0697	ctrutt@fundareresources.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430313	LOCATION	AC			-	Razor 27L Pad	RI
430326	WELL	PR	04/06/2013	OW	123-36130	Razor 27-3414H	RI
433652	WELL	PR	02/11/2014	OW	123-37730	Razor 27L-3401B	RI
433678	WELL	PR	09/01/2021	OW	123-37744	Razor 27L-3404B	RI
434379	WELL	PR	03/01/2022	OW	123-38130	Razor 27L-3403B	RI

General Comment:

This is an Interim Reclamation and Stormwater Inspection for Location ID 430313.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris (e.g. pipe fittings, trash, parts) observed throughout the location.		
Corrective Action:	Comply with Rule 606 and remove debris. Corrective action date is the date the location was observed out of compliance.	Date:	05/26/2023
Type	OTHER		
Comment:	Open top drum with visible hydrocarbon/fluid observed next to pumpjack. Drum did not have secondary containment or lid/cover.		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention per Rule 1002.f.(2)B. Or remove from location and properly dispose of oily waste per Rule 905.e. Corrective action date is the date the location was observed out of compliance.	Date:	05/26/2023
Type	WEEDS		
Comment:	Tumbleweed accumulations around flare observed during this inspection.		
Corrective Action:	Comply with Rule 606 and remove tumbleweed debris. Corrective action date is the date the location was observed out of compliance.	Date:	05/26/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 430313 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Facility ID: 430326 Type: WELL API Number: 123-36130 Status: PR Insp. Status: RI

Facility ID: 433652 Type: WELL API Number: 123-37730 Status: PR Insp. Status: RI

Facility ID: 433678 Type: WELL API Number: 123-37744 Status: PR Insp. Status: RI

Facility ID: 434379 Type: WELL API Number: 123-38130 Status: PR Insp. Status: RI

The subreport 'InspRecPit' could not be found at

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200309	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6133042