

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/26/2023

Submitted Date:

06/01/2023

Document Number:

708200286

## FIELD INSPECTION FORM

 Loc ID 431782 Inspector Name: Edwardson, Dylan On-Site Inspection  2A Doc Num:
**Operator Information:**
 OGCC Operator Number: 10773  
 Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC  
 Address: 5251 DTC PKWY STE 950  
 City: GREENWOOD State: CO Zip: 80111
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TRUITT, J CODY	281-513-0697	ctrutt@fundareresources.com	Principal Agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431782	LOCATION	AC			-	Razor 27K-3407A	RI
431783	WELL	PR	12/01/2021	OW	123-36773	RAZOR 27K-3407A	RI
433589	WELL	PR	08/14/2017	OW	123-37697	Razor 27K-3408B	RI
433607	WELL	PR	12/24/2013	OW	123-37708	Razor 27K-3406B	RI
433686	WELL	PR	05/01/2015	OW	123-37748	Razor 27K-3405A	RI

**General Comment:**

This is an Interim Reclamation and Stormwater Inspection for Location ID 431782.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	During this inspection, tumbleweed accumulations were observed around the flare unit.		
Corrective Action:	Comply with Rule 606 and remove tumbleweed debris. Corrective action date is the date the location was observed out of compliance.	Date:	05/26/2023
Type	DEBRIS		
Comment:	Degraded straw wattles observed on the southern portion of the location are now considered debris and will need to be removed.		
Corrective Action:	Comply with Rule 606 and remove debris. Corrective action date is the date the location was observed out of compliance.	Date:	05/26/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 431782 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 431783 Type: WELL API Number: 123-36773 Status: PR Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433589 Type: WELL API Number: 123-37697 Status: PR Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433607 Type: WELL API Number: 123-37708 Status: PR Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433686 Type: WELL API Number: 123-37748 Status: PR Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

The subreport 'InspRecPit' could not be found at

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200310	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6133043">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6133043</a>