

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2023

Submitted Date:

06/10/2023

Document Number:

708300556

FIELD INSPECTION FORM

 Loc ID 312615 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num:
Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222043	WELL	PR	03/01/2018	GW	077-08645	HORSESHOE CANYON 2-20	PR

General Comment:[COGCC Inspection Report Summary](#)

On 6/9/2023 at approximately 12:25, Compliance Inspector Matthew Morris conducted an on-site inspection at LARAMIE ENERGY LLC, Horseshoe Canyon/2-20 Pad at Location ID #312615 in Mesa County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Wildlife entry hazard in vertical separator

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Pipe rail fencing		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Damage at the base of separator is a wildlife entry hazard.		
Corrective Action:	Install wildlife protection screen on separator to comply with Rule 608		Date: 07/10/2023
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on Bradenheads. All Bradenhead valves are accessible.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 222043 Type: WELL API Number: 077-08645 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction						
		Sediment Traps				
		Berms				
		Culverts				
		Rip Rap				
		Check Dams				
		Gravel				
Gravel						
		Ditches				

Comment: [Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300557	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6142484