



00198137

H&R Well Services, Inc.
17509 RD. 14
Ft. Morgan, Colorado 80701
303-432-5285 or 654-1600 (Metro)

September 28, 1994

Al Arlian
Arlian, Inc.

RE: Lease: Thornton #2
SE/4 SE/4 Sec. 3-7N-54W
Logan County, Colorado

RECEIVED

OCT - 5 1994

COLO. OIL & GAS CONS. COMM.

Sirs,

We performed the following work on the above lease. This letter should be attached to a Form 4, and forwarded to the Colorado Oil & Gas Commission.

Set a CIBP at 4500' and spotted 2 sacks of cement.
Loaded the hole.
Freepoint and cut casing at 205'.
Pump cement 300' back to surface.
Set 10 sacks of cement at surface pipe.
Cut wellhead off 4' below surface, welded a plate.
Removed deadmen, backfilled the hole, cleaned up location.

Final lease restoration is the responsibility of the operator.

All cement was 50/50 poz, yield is 1.26 cu. ft./sack, weight is 14.1 ppg.

Sincerely,

Frank Hutto
H&R Well Services, Inc.

H&R Well Services, Inc.
17509 RD. 14
Ft. Morgan, Colorado 80701
303-432-5285 or 654-1600 (Metro)

September 28, 1994

Al Arlian
Arlian, Inc.

RE: Lease: Thornton #2
SE/4 SE/4 Sec. 3-7N-54W
Logan County, Colorado

Sirs,


We performed the following work on the above lease. This letter should be attached to a Form 4, and forwarded to the Colorado Oil & Gas Commission.

Set a CIBP at 4500' and spotted 2 sacks of cement.
Loaded the hole.
Freepoint and cut casing at 205'.
Pump cement 300' back to surface.
Set 10 sacks of cement at surface pipe.
Cut wellhead off 4' below surface, welded a plate.
Removed deadmen, backfilled the hole, cleaned up location.

Final lease restoration is the responsibility of the operator.

All cement was 50/50 poz, yield is 1.26 cu. ft./sack, weight is 14.1 ppg.

Sincerely,



Frank Hutto
H&R Well Services, Inc.

Thank You!

Thank You!