

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403446742

Date Received:
06/27/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696305027
Inspection Date: 06/20/2023 FIR Submit Date: 06/20/2023 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 323364

Location Name: LOST CREEK STATE-64N62W Number: 36SEnw County: WELD
Qtrqtr: SEnw Sec: 36 Twp: 4N Range: 62W Meridian: 6
Latitude: 40.270794 Longitude: -104.274589

FACILITY - API Number: 05-123-00 Facility ID: 245118

Facility Name: LOST CREEK STATE Number: 1
Qtrqtr: SEnw Sec: 36 Twp: 4N Range: 62W Meridian: 6
Latitude: 40.270794 Longitude: -104.274589

CORRECTIVE ACTIONS:

1 CA# 173373

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

Date: 05/12/2023

Response: CA COMPLETED Date of Completion: 06/21/2023

Back Drain Valve has been tightened. this response is for FIR Doc #696304855

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved Pending Re-Inspection

2 CA# 173374

Corrective Action: Install sign to comply with Rule 605.h.

Date: 06/09/2023

Response: CA COMPLETED

Date of Completion: 06/21/2023

Operator Comment: New tank labels have been installed. Please see attached picture. this response is for FIR Doc #696304855

COGCC Decision: Approved

COGCC Representative: Approved

3 CA# 173375

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

Date: 05/23/2023

Response: CA COMPLETED

Date of Completion: 06/20/2023

Operator Comment: Stained soil around valve has been removed. Please see attached pictures. this response is for FIR Doc #696304855.

COGCC Decision: Approved

COGCC Representative: Approved

4 CA# 173376

Corrective Action: Comply with Rule 606

Date: 05/23/2023

Response: CA COMPLETED

Date of Completion: 06/21/2023

Operator Comment: Unused Pipe and Valves at Tanks, debris and trash have been removed. this response is for FIR Doc #696304855

COGCC Decision: Approved

COGCC Representative: Approved

5 CA# 173377

Corrective Action: Comply with Rule 606

Date: 05/23/2023

Response: CA COMPLETED

Date of Completion: 06/21/2023

Operator Comment: All unmarked risers have been LOTO. Please see attached pictures. this response is for FIR Doc #696304855.

COGCC Decision: Approved

COGCC Representative: Approved

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering Tech

Date: 6/27/2023 1:07:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403446742	FIR RESOLUTION SUBMITTED
403446806	Risers tagged PIC1
403446809	CAs completed PIC2

Total Attach: 3 Files