

OFFICE OF STATE OIL INSPECTOR  
 SUNDRY NOTICES AND REPORTS OF WELLS  
 LOCATED ON PRIVATE LANDS

*1 Approved Copy  
 Returned 9-11-51  
 LB 3  
 292*



(Indicate nature of data by checking below)

- Notice of intention to drill..... XXXX
- Notice of intention to change plans.....
- Notice of date for test of water shut-off.....
- Report on result of test of water shut-off.....
- Notice of intention to re-drill or repair well.....
- Notice of intention to clean out well.....
- Statement of shooting.....
- Statement of perforating.....
- Notice to pull or otherwise alter casing.....
- Notice of intention to abandon well.....
- Report of work done on well since previous report.....

Following is a (notice of intention to do work) (On land) September 7 1951  
 (~~report of work done~~) (patented) described as follows:

<u>Colorado</u>	<u>Logan</u>	<u>Atwood</u>
State	County	Field
<u>J-9</u>	<u>Pomeroy</u>	<u>20 SE 1/4 SW 1/4 SE 1/4</u>
(Well No.)	(Lease)	(Sec. and 1/4 Sec.)
		<u>7N</u>
		(Twp.)
		<u>53W</u>
		(Range)
		<u>6th</u>
		(Meridian)

The well is located 330 ft. (N) of S and 1650 ft. (E) of E  
 (S) (W)

The elevation above sea level is To be furnished later. ft.

Details of Plan of Work: (State names of and expected depths to objective sands: Show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

We propose to drill a well on the above described land using rotary tools, the well to be known as Pomeroy Well #J-9. The proposed well will be drilled to the Dakota formation.

It is expected that approximately 150 ft. of 10-3/4", 8 Rd thd, 32.75# casing will be run as the surface string and cemented to the surface.

It is estimated that the Dakota formation will be found at 4700 ft below the rotary bushing. In the event a production string is needed, 5-1/2" OD 8 Rd. Thd, 14#, J-55 casing will be run thru the producing formation and the production zone will be perforated. The casing will be cemented with enough cement to conform with good engineering practice.

All measurements will be taken from the rotary bushing.

Approved: Sept 10, 1951

*John R. Brown*  
 State Oil Inspector

Company Trigood Oil Company 89990

Address Box 1689, Casper, Wyoming

By J. B. Burnett

Title mgr.

Submit reports of proposed work, for approval, on this form in Duplicate.

JDM/ib SOI (2) ; FLD; LD; JLF