

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2023

Submitted Date:

07/13/2023

Document Number:

702501639**FIELD INSPECTION FORM**

Loc ID 314355	Inspector Name: Burchett, Kirby	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 8 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10556</u> Name of Operator: <u>PLUG NICKEL OIL COMPANY INC</u> Address: <u>PO BOX 1937</u> City: <u>VERNAL</u> State: <u>UT</u> Zip: <u>84078</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Hogue, Jimmy	(435) 828-7666	hogue@stratanet.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228535	WELL	PR	04/01/2023	OW	103-05424	HUSKY 20	PR

**General Comment:**COGCC Inspection Report Summary

On Wednesday, 7/13/23, Inspector Kirby Burchett, conducted a follow up field inspection at Plug Nickel Oil Co. on the Husky 20 well, Location #314355, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501113 on 4/7/23. All Corrective Actions have been resolved.

While there during normal operations the following compliance issues were observed:

1. Oily rags.
2. Open valve on loadline.
3. Gearbox leak on pumping unit.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 435-828-7666 or 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Oily rags on tank landing		
Corrective Action:	Combustible materials such as oily rags and waste will be stored in covered metal containers.	Date:	07/21/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Oily waste from leak on pumping unit			
Corrective Action:	Repair leak. Remove and properly dispose of oily waste and impacted soil.	Date:	07/29/2023	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLS	STEEL AST		,

Comment:	Loadline and tank valves capped or plugged. Secondary valve on loadline left open.	
Corrective Action:	All loadlines or tank valves that can be used as a loadline will be capped or plugged.	Date: 07/19/2023

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 228535	Type: WELL	API Number: 103-05424	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Last production - April 2023			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501644	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6180837">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6180837</a>