

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2023

Submitted Date:

07/10/2023

Document Number:

699106859**FIELD INSPECTION FORM**Loc ID 471229 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10651Name of Operator: VERDAD RESOURCES LLCAddress: 1125 17TH STREET SUITE 550City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
471229	LOCATION	AC			-	KBL 02N-63-19	AC

**General Comment:**[Inspection on the Tank Battery](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Compressor skid will need to be cleaned in the near future		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Shed around compressor		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:	Day tank next to the compressor needs a bird protector "netting". See attached photo.		
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats. per rule 608.b.(7)	Date:	07/19/2023
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	ECOVapor		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Unmarked risers in multiple spots need to be marked. See attached photos		
Corrective Action:	Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser.		Date: 07/19/2023
Type: Vertical Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:	Recycle		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	FIBERGLASS AST		40.122700,-104.477700
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	30 BBLs
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	3	400 BBLs	FIBERGLASS AST			
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	400 BBLs	STEEL AST			
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 471229 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: Active Tank Battery

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

ECMC Inspection Report Summary  
 On Tuesday 7/5/23 at approximately 1027hrs I, Inspector Adam Burns,  
 Conducted an on-site inspection at KBL 02N-63-19 Tank Battery of VERDAD RESOURCES  
 LLC.  
 Location ID: 471229 in Weld County, Colorado.  
 During this inspection the following possible compliance issues were observed:  
 Day tank next to the compressor needs a bird protector "netting". All stacks, vents, or  
 other openings will be equipped with screens or other appropriate equipment to  
 prevent entry by wildlife, including birds and bats. Per rule 608.b.(7). With a CA date of 7  
 -19-23  
 Unmarked risers in multiple spots need to be marked. Upon removing a flowline or crude oil  
 transfer line from use with the intent to abandon, an operator must immediately apply  
 OOSLAT to the risers. OOSLAT must stay in place at all times during the process of  
 abandoning the flowline or crude oil transfer line until the operator removes the riser.  
 Comply with Rule 1105.b With a CA date of 7-19-23  
 A follow up on this site inspection needs to be conducted to ensure the  
 Compliance issues have been corrected to comply with ECMC rules.  
 This is a summary of the inspection report.

burnsa

07/10/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403457610	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6174288">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6174288</a>
699106860	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6174285">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6174285</a>