

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403459740

Date Received:

07/11/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Vanessa Fields</u>	<u>505-787-2218</u>	<u>vfields@logosresourcesllc.com</u>
<u>Etta Trujillo</u>	<u>505-324-4145</u>	<u>etrujillo@logosresourcesllc.com</u>
<u>Dacye Shull</u>	<u>505-787-2027</u>	<u>dshull@logosresourcesllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690204334

Inspection Date: 06/15/2023

FIR Submit Date: 06/16/2023

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 333537

Location Name: BONDAD 33-9-N33N9W Number: 4SENW County: LA PLATA

Qtrqr: SENW Sec: 4 Twp: 33N Range: 9W Meridian: N

Latitude: 37.135780 Longitude: -107.833590

FACILITY - API Number: 05-067-00 Facility ID: 214199

Facility Name: BONDAD 33-9 Number: 10

Qtrqr: SENW Sec: 4 Twp: 33N Range: 9W Meridian: N

Latitude: 37.135780 Longitude: -107.833590

CORRECTIVE ACTIONS:

1 ☒ CA# 173095

Corrective Action: Install or repair wildlife protection equipment.

Date: 06/15/2023

Response: CA COMPLETED

Date of Completion: 07/10/2023

Operator Comment: repaired wildlife protection equipment

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 173096

Corrective Action: Comply with Rule 1003.f.

Date: 06/15/2023

Response: CA COMPLETED

Date of Completion: 07/10/2023

Operator
Comment: location now complies with Rule 1003.f

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 173097

Corrective Action: Comply with 606

Date: 06/23/2023

Response: CA COMPLETED

Date of Completion: 07/10/2023

Operator
Comment: location now complies with 606

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 173098

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 05/05/2023

Response: CA COMPLETED

Date of Completion: 07/10/2023

Operator
Comment: BMP's installed and/or repaired

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: LOGOS resolved issues on Bondad 33-9 10. Vehicle rutting on access road was fixed, electric utility was fixed, noxious weeds were removed and tank netting was fixed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dacye Shull

Signed: _____

Title: Regulatory Technician

Date: 7/11/2023 9:37:23 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403459740	FIR RESOLUTION SUBMITTED
403459788	tank netting repaired
403459793	access road/vehicle rutting fixed
403459799	electrical utility repaired
403459802	electrical utility/weeds removed

Total Attach: 5 Files