

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2023

Submitted Date:

07/14/2023

Document Number:

698600718

FIELD INSPECTION FORMLoc ID 336736 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

21 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Fisher, Jeremy	970-520-8433	Jeremy_Fisher@omimexgroup.com	
Quint, Craig		craig.quint@state.co.us	
Lewis, Michelle	(817) 804-8902	michelle_lewis@omimexgroup.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159151	UIC DISPOSAL	AC	03/29/2006		-	BLED SOE SWD 1-18-3-43	AC
278717	WELL	IJ	04/01/2021	DSPW	125-09352	BLED SOE SWD 1-18-3-43	IJ

General Comment:

UIC Routine - 2023

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained county road.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank Battery placards are sun bleached and fading.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign located at well.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Buried plastic tank at injection room facility has no label or signage. Tank is full.		
Corrective Action:	Install sign to comply with Rule 605.g. Corrective action date adjusted due to inspector computer delay.		Date: 08/16/2023
Emergency Contact Number:			
Comment:	Repeated attempts to call posted emergency contact #877-425-4882. Number does not go through resulting in disconnect.		
Corrective Action:	Install sign to comply with Rule 605.d. Corrective action date adjusted due to inspector computer delay.		Date: 08/16/2023
Good Housekeeping:			
Type	OTHER		
Comment:	Current conditions at the facility are deteriorating due to lack of maintenance with vegetation growth (weeds/grass) and facility debris.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Deadman # & Marked	# 4	corrective date	
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Power pole.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Triplex pump.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Water filter.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Insulated wellhead building		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Metal Building - Injection control room containg Triplex injection pump and water fliter.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:	1 of 3 tanks.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Need maintenance to prevent deterioration.			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		FIBERGLASS AST		,
Comment:	3 of 3 tanks.				
Corrective Action:			Date:		

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		,	
Comment:	2 of 3 tanks.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 159151 Type: UIC API Number: - Status: AC Insp. Status: AC**Underground Injection Control**UIC Violation: Other Maximum Injection Pressure: 575UIC Routine

Inj./Tube: Pressure or inches of Hg 0 Previous Test Pressure _____ MPP _____
(e.g. 30 psig or -30" Hg) Inj Zone: _____

TC: Pressure or inches of Hg -10 Previous Test Pressure _____ Last MIT: _____

Brhd: Pressure or inches of Hg 0 Previous Test Pressure _____ AnnMTReq: _____

Comment: Tubing = 0 psi, Casing = -10 psi, BH = 0 psi. Last MIT 3/22/2021. Possible casing leak. All injection wells which fail MIT or which are determined to lack mechanical integrity shall be shut in. Unable to reach Operator at emergency contact number 877-425-4882.

Corrective Action: Immediately shut in well and disconnect flowline or disable/LOTO injection pump. Date: 07/14/2023

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 278717 Type: WELL API Number: 125-09352 Status: IJ Insp. Status: IJ

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No storm water issues noted at time of inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<u>Corrective action dates were adjusted to make allowance for delays with inspectors computer and computer software issues. Several attempts were made to directly contact Operator all unsuccessful.</u>	stjohnw	07/14/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403465450	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182053
698600748	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182042