

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/28/2023

Submitted Date:

07/28/2023

Document Number:

696305171

FIELD INSPECTION FORM
 Loc ID 428699 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10671

Name of Operator: EDGE ENERGY II LLC

Address: 600 12TH STREET SUITE 115

City: GOLDEN State: CO Zip: 80401

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Turner, Ben		bturner@edgeenergy1.com	ALL INSPECTIONS
Welch, Kelsi		Kelsi.welch@iptwell.com	ALL INSPECTIONS
Larsen, Erik		elarsen@edgeenergy1.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428700	WELL	SI	02/01/2022	OW	123-35475	WASHBURN GX 15-62HN	SI

General Comment:

Folllow-Up Inspection to FIR 696305077 dated 07.06.2023 and in response to FIRR 403469479 dated 07.19.2023

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate - 300 BBIs Produced Water Tank now has Adequate Capacity Label		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Riser at ECD has been marked		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Weeds REMAIN at ECD and East of ECD Overhead Line - NOTE ALL WEEDS MUST BE CUT DOWN OR REMOVE ON ENTIRE LOCATION. See photos		
Corrective Action:	Comply with Rule 606	Date:	08/11/2023
Type	WEEDS		
Comment:	Tumbleweed Debris at South Separator and East of Separators - NOTE ALL TUMBLEWEED DEBRIS MUST BE REMOVED FROM ENTIRE LOCATION. CHECK AT REGULAR INTERVALS TO INSURE TUMBLEWEED DEBRIS DOES NOT ACCUMULATE. See Photos		
Corrective Action:	Comply with Rule 606	Date:	08/11/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 428700 Type: WELL API Number: 123-35475 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Routine Field Follow-Up Inspection. Tumbleweeds at South Separator and East of Separator Berm. Weeds STILL REMAIN at ECD and East of ECD Overhead Line.	petrie	07/28/2023
* NOTE ALL WEEDS MUST BE CUT DOWN OR REMOVE ON ENTIRE LOCATION		
* NOTE ALL TUMBLEWEED DEBRIS MUST BE REMOVED FROM ENTIRE LOCATION. CHECK AT REGULAR INTERVALS TO INSURE TUMBLEWEED DEBRIS DOES NOT ACCUMULATE		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403480089	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6198367
696305172	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6198362