

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

Document Number:
 403485691
 Date Received:

OGCC Operator Number: 10633 Contact Name: Adam Conry
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (303) 883-3351
 Address: 1801 CALIFORNIA STREET #2500 Fax: _____
 City: DENVER State: CO Zip: 80202 Email: AConry@civiresources.com

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 Email: _____
COGCC contact:

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-005-06549-00
 Well Name: BOX ELDER-STATE Well Number: 4-10
 Location: QtrQtr: NWNW Section: 10 Township: 5S Range: 64W Meridian: 6
 County: ARAPAHOE Federal, Indian or State Lease Number: 70-8004-S
 Field Name: WILDCAT Field Number: 99999

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.635685 Longitude: -104.544988
 GPS Data: GPS Quality Value: 0.0 Type of GPS Quality Value: Accuracy in Meters Date of Measurement: 07/07/2023
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	124	80	124	0	VISU
OPEN HOLE	7+7/8				124	8346				

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 100 sks cmt from 7514 ft. to 7314 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 50 sks cmt from 3200 ft. to 3100 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 175 sks cmt from 2053 ft. to 1505 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 50 sks cmt from 908 ft. to 808 ft. Plug Type: OPEN HOLE Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
Set 310 sacks half in. half out surface casing from 285 ft. to 0 ft. Plug Tagged:
Set 10 sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: 7
Surface Plug Setting Date: 07/20/2023 Cut and Cap Date: 07/27/2023

*Wireline Contractor: _____ *Cementing Contractor: Axis

Type of Cement and Additives Used: Class G, Thixo

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

- Venting health and safety precautions were taken to avoid nuisance and or hazards to the public.
- Form 42 was submitted prior to plugging operations, Form 42 Doc # 403461114. Form 42 was submitted prior to MIRU for plugging operations, Form 42 Doc # 403461112.
- Prior to placing plug at 3100', operator waited a sufficient amount of time to confirm static conditions. There was no pressure or fluid migration.
- No fluids or gas migration was present prior to cement plug to surface being set. The plug was cemented to surface with 310 sacks of cement from 285' - 0' and a minimum of 10 sxs of cmt was pumped at surface.
- At least 100' of cement was left in the wellbore for each plug.
- This form 6-SRA addresses all COA's from the Form 6-NOIA.
- As Drilled GPS Data & Lat/Long has been updated on the Form 6-SR Well Info Panel. 39.635685, -104.544988. Verification attached.

Attached to this form:

1. Cement tickets are attached to this form.
2. Operations summary is attached to this form for reference.
3. Final P&A WBD is attached to this form.
4. As-Drilled GPS Data is attached to this form

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Ashley Noonan
Title: Sr. Regulatory Analyst Date: _____ Email: regulatory@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____

<u>COA Type</u>	<u>Description</u>
0 COA	

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403485839	WELLBORE DIAGRAM
403485840	OTHER
403485841	CEMENT JOB SUMMARY
403485842	OPERATIONS SUMMARY

Total Attach: 4 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)