

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403488638

Date Received:

08/08/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: 501 N DIVISION BLVD

City: PLATTEVILLE State: CO Zip: 80651

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Toni.Newville@oxy.com

COGCCInspections@Oxy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 697504773

Inspection Date: 08/01/2023

FIR Submit Date: 08/03/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER

State: CO

Zip: 80217-3779

### LOCATION - Location ID: 481939

Location Name: PAUL NELSON

Number: 25-29HZ

County: \_\_\_\_\_

Qtrqtr: NWSE

Sec: 29

Twp: 5N

Range: 67W

Meridian: 6

Latitude: 40.368439

Longitude: -104.915654

### FACILITY - API Number: 05-123-00

Facility ID: 481939

Facility Name: PAUL NELSON

Number: 25-29HZ

Qtrqtr: NWSE

Sec: 29

Twp: 5N

Range: 67W

Meridian: 6

Latitude: 40.368439

Longitude: -104.915654

### CORRECTIVE ACTIONS:

1 ☒ CA# 177177

Corrective Action: Immediately comply with Rule 1002.e.(1) and Rule 1002.f. as this is threatening the complainants septic system and causing property damage.

Date: 08/01/2023

If the Operator fails to conduct immediate corrective actions, this matter will be forwarded onto Enforcement.

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 08/05/2023

Operator Comment: Reference attached completion report. KMOG evaluated unaffiliated drainage from the applicable agricultural field and installed a straw bale barrier along the neighboring fence line of the complainant property to serve as energy dissipation for the uncontrolled tail waters. This is a temporary measure due to safety working within a pressurized lay flat line. Additional mitigation measure may be implemented once the line is done with its current completions services and temporarily offline for equipment move.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: ATTN: Chris Binschus

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Austin Lee

Signed: \_\_\_\_\_

Title: Advisor HSE Environ Ops

Date: 8/8/2023 7:15:15 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403488638	FIR RESOLUTION SUBMITTED
403488651	Work completion report

Total Attach: 2 Files