

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403496499

Date Received:
08/15/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 12 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>COGCC.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205079
Inspection Date: 06/28/2023 FIR Submit Date: 07/06/2023 FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 479149

Location Name: BJU Number: B26-496 County: _____
Pad
Qtrqr: NENW Sec: 26 Twp: 4S Range: 96W Meridian: 6
Latitude: 39.677052 Longitude: -108.138400

FACILITY - API Number: 05-045-00 Facility ID: 479149

Facility Name: BJU Number: B26-496
Pad
Qtrqr: NENW Sec: 26 Twp: 4S Range: 96W Meridian: 6
Latitude: 39.677052 Longitude: -108.138400

CORRECTIVE ACTIONS:

1 CA# 174723

Corrective Action: Control spills and clean/remediate stained soils to Table 915-1 standards.

Date: 06/28/2023

Due to the ammount of spills observed throughout the Location, and the size of the apparent staining observed at the base of the tanks, Operator shall submit a Form 19, Spill/Release report pursuant to Rule 912.b.(1)G

The "Date of Discovery" is being provided as the corrective action date. Location will remain out of compliance until corrective action is resolved.

Response: CA COMPLETED

Date of Completion: 07/15/2023

Operator Comment: Spilled cuttings and stained soils cleaned up and placed back into cuttings containment.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 174724

Corrective Action: Comply with Rule 606- remove and properly dispose of trash/rubbish/waste material improperly stored on the Location; remove and properly dispose of potentially impacted trash/rubbish/waste material improperly buried and placed within the Cuttings Trench.
The "Date of Discovery" is being provided as the corrective action date. Location will remain out of compliance until corrective action is resolved.

Date: 06/28/2023

Response: CA COMPLETED Date of Completion: 07/15/2023

Operator Comment: Debris cleaned up and removed from location.

COGCC Decision: _____

COGCC Representative: _____

11 CA# 174733

Corrective Action: Comply with Rule 1002.f and Rule 902. The "Date of Discovery" is being provided as the corrective action date. Location will remain out of compliance until corrective action is resolved.

Date: 06/28/2023

Response: CA COMPLETED Date of Completion: 07/15/2023

Operator Comment: Cuttings berm repaired and compacted.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden Signed: _____

Title: EHS Date: 8/15/2023 6:50:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files