

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2023

Submitted Date:

08/17/2023

Document Number:

712700531

**FIELD INSPECTION FORM**Loc ID 311965 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216476	WELL	PR	08/12/1997	CBM	067-08082	T.H. 32-7 12-1	PR
290382	WELL	PR	11/09/2007	CBM	067-09361	TIFFANY 32-7-12 8	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #702500654 submitted on 10/24/2022.

Equipment inventory listed on previous FIR, location equipment unchanged.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Present		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Landowner appears to be storing trailer on location, located ~60' from wellhead. See Photos #2 7 #3. Corrective action identified in FIR Doc.#702500654 has not been completed. Corrective action date has been retained.		
Corrective Action:	Remove trailer per Rule 502.		Date: 01/24/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 216476 Type: WELL API Number: 067-08082 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 06/22/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 290382 Type: WELL API Number: 067-09361 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 06/22/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Pass			
Compaction	Pass	Culverts	Pass			
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Landowner trailer appears similar to previous inspection photos. No variance pursuant to Rule 502 for a Surface Owner to use portions of the Oil and Gas Location in wellfile per Rule 606.a(2).	pattillc	08/17/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700535	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223568</a>