



01195024

FND. GLO BRASS CAP
3 N1/4 CORNER

-FND. BLM BRASS CAP
W1/4 SEC.7, T34S-R43W

DATE **5/20/04**

OPERATOR **SANDLIN OIL CORP.**

WELL NAME **MAYBERRY #1**

LOCATION **NW/4 SEC.10, T34S-R41W**

FOOTAGES & **666.6'** F N I

RELATIONS	<u>1986.4'</u>	<u>F</u>	<u>W</u>	<u>L</u>
-----------	----------------	----------	----------	----------

ELEVATION TOP OF CASING: **3631.0'**

GRADE: **3635.7'**

DISTANCE TO EXISTING WELL	
N/A	N/A

AUTHORIZED BY **G.SANDLIN**

Sandlin Oil Co.
Mayberry #1

PASTURE

FND. GLO BRASS CAP
MILEPOST 195

B41W

R43W

**BACA CO.
COLORADO**

MORTON CO. 8

KANSAS

(N 00°02'00" E)

**NW/4 SECTION 10, T34S-R41W
BACA COUNTY, COLORADO
PASTURE**

CROP	PASTURE
------	---------

WATER WELL

NEAREST TOWER

AIRPORT

LATITUDE 37°06'17.61290"N

LONGITUDE **102°02'51.23010"W**

STATE PLANE COORD. **X=4006652.21**
COLORADO SOUTH ZONE
NAD 83 **Y=1177667.22**

$$Y=1177667.22$$

DRIVING DIRECTIONS USED TO STAKE
WELL FROM KNOWN LANDMARK OR CITY
FROM: **FROM INTERSECTION STATE**
HWY. 27 AND HWY. 51 IN KANSAS,
WEST 8.0 MILES TO KAN.-COLO. STATE
LINE THENCE SOUTH 3.85 MILES
THENCE WEST 1610 FEET INTO



NOTE: CONTRACTOR TO CONTACT UTILITY NOTIFICATION OF COLORADO @
1-800-922-1987 PRIOR TO ANY EXCAVATION OR CONSTRUCTION.

Theodore V. Harder P.L.S. NO. 28271



Sandlin Oil Corp.

621 17th STREET
DENVER, COLO.
Ph.: (303)324-3909
Fax: (303)292-3969

**WELL LOCATION OF THE MAYBERRY #1
LOCATED IN THE NW/4 SEC.10, T34S-R41W
BACA COUNTY, COLORADO**

DRAWN BY: AEP	CHECKED BY: TVH	APPROVED BY:	AUTHORIZED BY: G. SANDLIN
------------------	--------------------	--------------	------------------------------

NO.	OWN.	REVISIONS	DATE
SCALE:		1" = 1500'	DATE: 5/20/04
WORK ORDER NO.:			

HARDER

AND ASSOCIATES
Consulting, Engineering & Land Surveying
P.O. BOX 518 406 MORTON
ELKHART, KANSAS 67950
Phone: (620) 697-2696
Fax: (620) 697-4175

DRAWING NO. BA054A09