

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2023

Submitted Date:

08/31/2023

Document Number:

702501773

**FIELD INSPECTION FORM**Loc ID 314769 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10605

Name of Operator: APEX OIL VENTURES INC

Address: 8823 S. REDWOOD ROAD #D-1

City: WEST JORDAN State: UT Zip: 84088

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rasmussen, Terry	(801) 487-4721	t.rasmussen@outlook.com	
Callister, Andrew	(801) 455-8366	andy@qualituoilproperties.com	
Callister, Jan E	(808) 571-5890	jec-apex@outlook.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229526	WELL	PR	04/16/2007	OW	103-07182	GILLAM-TRIGOOD- GOV'T 14	PR

**General Comment:****ECMC Inspection Report Summary**

On Tuesday, 08/23/2023, Inspector Kirby Burchett, conducted a routine field inspection at APEX Oil Ventures Inc on the Gillam-Trigood-Gov't 14 well, Location #314769, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

1. Debris
  2. Weeds
  3. Stained soil
  4. Stormwater BMPs
  5. No sign at tank battery. Tank battery is offsite.
- Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No sign at tank battery.		
Corrective Action:	The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s); and Location, including the quarter/quarter section, of the Tank battery.	Date:	09/23/2023

Emergency Contact Number:

Comment: 801-571-5890 / 970-620-2257 / 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.		
Corrective Action:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.	Date:	08/31/2023
Type	DEBRIS		
Comment:	Random debris on pumping unit and around tank battery		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.	Date:	08/31/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Truck Loadout	<= 1 bbl	
Comment:	Stained soil at below loadout pot.		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 09/08/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Gauge installed		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	HEATED STEEL AST		,
Comment:	Tank battery is separate location from Gillam-Trigood-Gov't 14 well				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined. Heavy sediment runoff into containment due to location and lack of Stormwater BMPs.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	Ignitor/Combustor	
Comment:	All gas is flared through combustor on tank battery location.	
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 229526	Type: WELL	API Number: 103-07182	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater BMPs need implementation and maintenance.](#)

Corrective Action: [Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Date: 09/23/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501774	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238984">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238984</a>