

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2023

Submitted Date:

08/24/2023

Document Number:

694500588

FIELD INSPECTION FORMLoc ID 324641 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 34162

Name of Operator: GILS HOT OIL SERVICE

Address: P O BOX 418

City: STRASBURG State: CO Zip: 80136

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Paine, Gilbert	303709-0148	cherokeeequipment@hotmail.com	
Ramsey, Scott		scott.ramsey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212246	WELL	PR	05/01/2021	OW	057-06139	STATE 5	EI

General Comment:

Any Corrective Actions from previous Inspections that have not been addressed are still applicable. On 8/3/23, C-ECMC staff, Kris Neidel was on location to inspect the State 5 Well. The well was SI at the time of inspection. The following was observed. Pumping unit on a ground with one end on wood. Well has a wired up pump rod as a fence. Flowlines: there is a shallow buried line from the wellhead to tank, There is a 200bbl tank that has NO secondary containment. The soil at the tank battery is Sand. Lack of secondary containment was documented on Inspection 707800362, 5/12/23 and inspection going back to at least 2011, doc 200325508. See attached Photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	200 BBLs	STEEL AST		,	
Comment: Secondary containment is insufficient						
Corrective Action: Repair or install berms or other secondary containment devices						Date: 06/23/2023

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Secondary containment is insufficient				
Corrective Action: Repair or install berms or other secondary containment devices				
Date: 06/23/2023				

Venting:

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected FacilitiesFacility ID: 212246 Type: WELL API Number: 057-06139 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500589	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239927