

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2023

Submitted Date:

09/07/2023

Document Number:

713600206

**FIELD INSPECTION FORM**

Loc ID 416357 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74165  
 Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
 Address: 6155 S MAIN STREET #225  
 City: AURORA State: CO Zip: 80016

**Findings:**

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
INGVE EDWARD		ed@renegadeoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416366	WELL	PR	03/01/2019	GW	099-06909	IDLER B 2X	RI
446543	TANK BATTERY	AC	07/08/2016		-	IDLER B 2X	RI

**General Comment:**

On 9/6/2023, Ryan Costa conducted a follow up location inspection. See attached photos and additional details within this report.

Previous corrective actions have not been completed. Operator is directed to perform corrective actions outlined on this inspection report immediately.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	There is no sign posted at the tank battery. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	07/11/2023
Type	BATTERY		
Comment:	The tank labeling is inaccurately posted as water and there are signs of crude oil in the tank. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.h. and accurately show contents in the tank.	Date:	07/11/2023

**Emergency Contact Number:**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			
Crude Oil	Tank				
Comment:	There is oil stained soil at the base of the tank that needs to be cleaned up. Previous corrective action was not completed.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date:	07/11/2023

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	200 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	There is insufficient secondary containment at the tank battery. Previous corrective action was not completed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	07/11/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600207	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6244437">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6244437</a>