

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/11/2023

Submitted Date:

09/11/2023

Document Number:

708901608

FIELD INSPECTION FORM
 Loc ID 430758 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Mustang		dlemon@mustangresourcesllc.com	
, Mustang		bcoutts@mustangresourcesllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210815	WELL	PR	10/01/2020	GW	045-06573	CLOUGH 27-11-6S-94W	PR

General Comment:**CECMC Inspection Report Summary**

On 09/11/2023 at approximately 09:52 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at MUSTANG RESOURCES LLC CLOUGH 27-11-6S-94W Pad.

Location # 430758 in Garfield County Colorado.

Location is within High Priority Habitat area & Bald Eagle Nest & Roost sites & within close proximity to NSO/Density Habitat areas.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Unmarked deadman with a CA date of 09/25/2023

2. Stormwater - Lack of stabilization/compaction on location with a CA date of 09/26/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/1-888-291-8588

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:	Well is not on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	1 marked deadman & 1 unmarked deadman		
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.	Date:	09/25/2023

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 210815	Type: WELL	API Number: 045-06573	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing, well is not on plunger lift			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Compaction	Fail					Lack of stabilization/compaction on location
		Ditches				
Gravel						Sparse to none
		Gravel				Sparse
		Compaction				

Comment: 1. Lack of stabilization/compaction on location/insufficient BMP's

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 09/26/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Equipment & Stormwater for observed compliance issues.	smelserw	09/11/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901609	Inspection 708901608 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247362
708901610	Inspection 708901608 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247363