

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403526804

Date Received:
09/14/2023

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 98220
Name of Operator: YOUNG GAS STORAGE COMPANY LTD
Address: P O BOX 1087
City: COLORADO SPGS State: CO Zip: 80944

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TRINKO, ANTHONY</u>		<u>anthony_trinko@kindermorgan.com</u>
		<u>logan.hansen@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200540
Inspection Date: 09/05/2023 FIR Submit Date: 09/08/2023 FIR Status: _____

Inspected Operator Information:

Company Name: YOUNG GAS STORAGE COMPANY LTD Company Number: 98220
Address: P O BOX 1087
City: COLORADO SPGS State: CO Zip: 80944

LOCATION - Location ID: 395839

Location Name: YOUNG-64N58W Number: 11NENE County: _____
Qtrqtr: NENE Sec: 11 Twp: 4N Range: 58W Meridian: 6
Latitude: 40.331870 Longitude: -103.832832

FACILITY - API Number: 05-087-00 Facility ID: 395839

Facility Name: YOUNG-64N58W Number: 11NENE
Qtrqtr: NENE Sec: 11 Twp: 4N Range: 58W Meridian: 6
Latitude: 40.331870 Longitude: -103.832832

CORRECTIVE ACTIONS:

1 CA# 180590

Corrective Action: Comply with Rule 1004. Location will remain out of compliance until the corrective action has been resolved. Date: 09/05/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: Operator does not own or operate the location

Operator Comment: Young's response to FIR Document Number 708200540 is attached to this document.

COGCC Decision: **Not Approved**

COGCC Representative: The inspection corrective actions do not relate to the operations at the wellbore. The location will remain out of compliance until the corrective action has been completed, per the 1000 Series Rules.

COGCC Supervisor: The inspection corrective actions do not relate to the operations at the wellbore. The location will remain out of compliance until the corrective action has been completed, per the 1000 Series Rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Young's response to FIR Document Number 708200540 is attached to this document.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Anthony P. Trinko

Signed: _____

Title: Sr. Reservoir Engineer

Date: 9/14/2023 4:40:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403526804	FIR RESOLUTION SUBMITTED
403530824	Young Response to FIR Document #708200540

Total Attach: 2 Files