



00566822

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.
 Land Office Denver
 Lease No. Colo. 03404
 Unit Gilliam Draw

 (SUBMIT IN TRIPLICATE)
 AUG 8 - 1958
 UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 24, 1958

Gilliam
Well No. 4 is located 1890 ft. from N line and 2087 ft. from E line of sec. 25

SW NW SE Sec. 25 1N 102W 6 PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Gilliam Draw Rio Blanco Colorado
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5852 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-28-58: PTD 0 Well P&A. Ran DP open ended to TD 6200, spotted 50 sx cement plug to 6050, 50 sx plug 2% Cal Chl. at 1675, let set 8 hrs. Tagged top cement at 1550, spotted 35 sx cement plug 375-270, placed 10 sx plug in top of surface and erected dry hole marker.

AJJ	
DVR	
WRS	
HHM	
JAM	
FJP	
JJD	
FILE	

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum
 Address P. O. Box 2331
Casper, Wyoming

By [Signature]
 Title District Superintendent