



Form 3160-5  
November 1983)  
Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

00063698

ICATE  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

# SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Twin Arrow, Inc. (303) 675-8226		8. FARM OR LEASE NAME Newton
3. ADDRESS OF OPERATOR P.O. Box 948 Rangely, CO 81648		9. WELL NO. #16A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2155' FNL, 1525' FWL, Sec. 12		10. FIELD AND POOL, OR WILDCAT Rangely-Mancos
14. PERMIT NO.		11. SEC. T. R. M. OR B.L. AND SURVEY OR AREA Sec. 12-T1N-R012W 6th pm.
15. ELEVATIONS (Show whether DP, ST, GR, etc.)		12. COUNTY OR PARISH 13. STATE Rio Blanco Colorado

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON & PLUG ☒CHANGE PLANS ☐

### SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

A field inspection trip was made 11-08-85 with the B.L.M. (Alan Schroeder) and Twin Arrow, Inc. (Don Miller, Trenton Day, and Tom Humes). There is a well location and surface pipe at the above location (I checked with a transit later), which fits "The well completion report" sent in 6-21-57. Twin Arrow, Inc. proposes to finish plugging this well with "Ready Mix cement", (approximately 25 feet of 7"), install Dry Hole Marker, remove dead men, rehabilitate location and send in subsequent report of final plug and abandoned work done.

This leaves us with another problem, Twin Arrow, Inc. has a producing oil well (Newton #16A) 1920' FNL, 1390' FWL, Sec. 12-T1N-R012W which was on the geological survey map made in 1962. I can find nothing in Twin Arrow's files that come any closer than 300' to this location. It appears that we will have to renumber this well.

18. I hereby certify that the foregoing is true and correct

SIGNED

Trenton Day

TITLE Production Foreman

DATE

11/21/85

(This space for Federal or State office use)

APPROVED BY

Elizabeth Allen

TITLE

Acting BLM Minerals

DATE

12/5/85

CONDITIONS OF APPROVAL, IF ANY:

STIPULATIONS  
ATTACHED

\*See Instructions on Reverse Side

FILE COPY