

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2023

Submitted Date:

09/12/2023

Document Number:

697504828

FIELD INSPECTION FORM

Loc ID 421908 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10665
Name of Operator: CCRP OPERATING INC
Address: 12136 W BAYAUD AVE STE 320
City: LAKEWOOD State: CO Zip: 80228

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		janderson@rockiesresourcesllc.com	
		cduran@rockiesresourcesllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421912	WELL	SI	02/01/2021	OW	123-33110	Wagner 11-65 11-1H	RI

General Comment:

This is an Interim Reclamation and Stormwater inspection in response to a Form 42 Doc.# 403503817 Start of Plugging Operations notice.
Note- Due to ECMC database migration, this inspection is delayed in being submitted.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment:

Unmanaged weeds were observed along an approximate 0.65 mile section of road and throughout portions of the location. Refer to the attached inspection photos.

Corrective Action:

Comply with Rule 606.c. The corrective date is the date the location was observed out of compliance.

Date: 08/29/2023

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 421912 Type: WELL API Number: 123-33110 Status: SI Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment **This location does not comply with Reclamation rules. Rule 1002.c. Topsoil stockpile has significant weed cover- Russian thistle and Kochia- with no perennial vegetation that would compete with the weedy vegetation and generally work to decrease weed growth.**
Note- Operator is scheduled to perform final reclamation activities during the month of September.

Corrective Action **Comply with Rule 1002.c. Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles.**

Date **08/29/2023**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? Fail
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
 Production areas have been stabilized? _____ Segregated soils have been replaced? Fail

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? F

Comment This location does not comply with Rule 1003.b. Operator has failed to perform interim reclamation to reduce disturbance areas only reasonably needed for production operations.

Note- Operator is scheduled to perform final reclamation activities during the month of September.

Corrective Action Operator can come into compliance with Interim Reclamation rules by performing the planned final reclamation activities during the month of September. Date 08/29/2023

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: _____	Date _____
Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/>
	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Stormwater erosion is coming off the access road and causing erosion into Willow Creek on the southern portion of the access road.</p> <p>Corrective Action: Comply with Rule 1002.f Date: 08/29/2023</p> <p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

COGCC Comments

Comment	User	Date
ECMC staff, Chris Binschus, contacted and communicated the observations of the inspection to an Operator representative on August 29, 2023. Staff indicated that the inspection would likely be delayed due to a database migration and staff PTO. On September 11, 2023, Staff received an update from the Operator stating that all corrective actions have been addressed regarding weed management and stormwater management.	binschusc	09/12/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403527662	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6248648
697504829	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6248639