

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403533970

Date Received:
09/19/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>COGCC.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708901335
Inspection Date: 08/08/2023 FIR Submit Date: 08/13/2023 FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334576

Location Name: COUEY-67S93W Number: 13SESE County: _____
Qtrqtr: SESE Sec: 13 Twp: 7S Range: 93W Meridian: 6
Latitude: 39.440140 Longitude: -107.718060

FACILITY - API Number: 05-045-00 Facility ID: 334576

Facility Name: COUEY-67S93W Number: 13SESE
Qtrqtr: SESE Sec: 13 Twp: 7S Range: 93W Meridian: 6
Latitude: 39.440140 Longitude: -107.718060

CORRECTIVE ACTIONS:

1 CA# 178369

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved. Date: 08/28/2023

Response: CA COMPLETED Date of Completion: 08/23/2023

Operator Comment: Removed sediment from culvert and repaired erosion and installed rock armoring inlet and outlet. Repaired rip rap run erosion and reinstalled rock armoring. Repaired erosion of location N/NW edge and installed armored outlet. Also repaired erosion on off east edge of location and installed armored outlet. See photos.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 9/19/2023 7:27:46 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403533977	Culvert repaired; armoring installed.
403533978	Culvert repaired; armoring installed.
403533979	Culvert repaired; armoring installed.

Total Attach: 3 Files