



00566003

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Burner  
Lease No. 033804 B  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	X	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

6 (see below) May 22, 1957  
Well No. 11 is located 1056 ft. from N line and 1056 ft. from E line of sec. 11  
3E 1/4 of SE 1/4 - 11 1-N 102W 6 PM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Rangely Rio Blanco Colorado  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well is #6 as reported by O M Heggen  
We intend to fish for lost tools and  
deepen, not to exceed 3300'

Approved 5/27/57  
J. J. Esquier  
District Engineer

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Newton Oil Co

Address \_\_\_\_\_

By Jack White

Title Operator

Box 457 Rangely Colo