

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2023

Submitted Date:

09/22/2023

Document Number:

710500018

FIELD INSPECTION FORMLoc ID 307344 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119868	PIT	AC			-	Laura 41-12	EI
217518	WELL	PR	07/30/1995	CBM	071-06295	LAURA 41-12	EI

General Comment:

This is an Environmental Inspection for the Laura 41-12; Location # 307344, active well location, located in Las Animas County, Co

Inspected Facilities									
Facility ID:	119868	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	217518	Type:	WELL	API Number:	071-06295	Status:	PR	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 119868Lat: 37.191122Long: -104.724375Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: NOComment: Offsite Pit Freeboard not maintained. IMMEDIATE ACTION IS REQUIRED.
Operator must monitor water level in pit to ensure 2 ft. freeboard at all times.Corrective Action: Comply with Rule 909.c., Maintain two foot of freeboardDate: 09/22/2023

Permit:	Facility ID	Permit Num	Expiration Date
	257516	848456	

Monitoring:	Monitoring Type	Comment
	Chain	Lower section of chain underwater

COGCC Comments

Comment	User	Date
File Form 15 to Update Pit Coordinates	sanchezcc	09/20/2023
Comply with Rule 909.c., Maintain two foot of freeboard. Lower section of chain underwater	sanchezcc	09/20/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
710500019	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6260497