

State of Colorado
Energy & Carbon Management Commission



Document Number:
403539571

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
09/25/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
General		FarmingtonRegulatoryTechs@hilcorp.com
Labowskie, Steve		steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 712700655
Inspection Date: 09/13/2023 FIR Submit Date: 09/14/2023 FIR Status:

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 312052

Location Name: ANIMAS 34-10-M34N10W Number: 36NWSE County: LA PLATA
Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M
Latitude: 37.144340 Longitude: -107.881820

FACILITY - API Number: 05-067-00 Facility ID: 297003

Facility Name: ANIMAS 34-10 Number: 36-1A
Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M
Latitude: 37.144340 Longitude: -107.881820

CORRECTIVE ACTIONS:

1 CA# 181122

Corrective Action: Remove if not needed for ongoing operations. Date: 09/29/2023

Response: CA COMPLETED Date of Completion: 09/22/2023

Operator Comment: Removed chemical trailer and reconnected muffler on Animas 34-10 #36-2A to satisfy unused equipment section of the INC.

COGCC Decision:

COGCC
Representative:

2 CA# 181123

Corrective Action: Return to service or remove as unused equipment.

Date: 10/14/2023

Response: CA COMPLETED

Date of Completion: 09/22/2023

Operator Comment: Removed chemical trailer and reconnected muffler on Animas 34-10 #36-2A to satisfy unused equipment section of the INC.

COGCC Decision:

COGCC
Representative:

3 CA# 181124

Corrective Action: Install sign to comply with Rule 605.a.

Date: 11/14/2023

Response: CA COMPLETED

Date of Completion: 09/22/2023

Operator Comment: Moved fenced enclosure back around Animas 34-10 36-1 to satisfy the signage and unused equipment(pipe fence) section of the INC.

COGCC Decision:

COGCC
Representative:

4 CA# 181125

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.

Date: 09/29/2023

Response: CA COMPLETED

Date of Completion: 09/22/2023

Operator Comment: Installed Spill containment to satisfy that section of the INC.

COGCC Decision:

COGCC
Representative:

5 CA# 181126

Corrective Action: Mark all guy anchors or remove if not serviceable or not needed for ongoing operations per Rule 1003.a.

Date: 09/28/2023

Response: CA COMPLETED

Date of Completion: 09/22/2023

Operator Comment: Installed Markers on the rig anchors across all 3 locations to satisfy that part of the INC.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:



I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty Signed: _____

Title: OperationsRegulatory Tech Date: 9/25/2023 9:01:25 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403539574	ANIMAS 34-10 36-2A_712700655_Resolved Photos

Total Attach: 1 Files