

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2023

Submitted Date:

09/25/2023

Document Number:

697008064

FIELD INSPECTION FORM

Loc ID 440858 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442120	WELL	AL	03/25/2020	LO	123-41686	Simpson FD 16-062HC	AL

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Other

1

corrective date

Comment: [Cellar ring remains on location, see attached photos.](#)

Corrective Action: [Remove cellar ring per Rule 406.\(4\)D.](#)

Date: 10/31/2023

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 442120 Type: WELL API Number: 123-41686 Status: AL Insp. Status: AL

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 9/25/2023 at approximately 12:20 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Simpson FD 16-062HC API #123-41686 in Weld County, Colorado. While there, I observed that the cellar ring remained on location. The following possible compliance issues were observed: Rule 406(4)D. with a corrective action date of 10/31/2023. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	09/25/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697008065	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6263408