

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2023

Submitted Date:

09/19/2023

Document Number:

710500010

**FIELD INSPECTION FORM**Loc ID 484359 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	
Butler, Brad	972-345-9195	butleroil@yahoo.com	Desert Eagle Operating llc
Bulf, Cathy		cathybulf@gmail.com	Desert Eagle Operating llc
Beardslee, Tom		tom.beardslee@state.co.us	

**General Comment:**

This is an Environmental Inspection for the Red Rocks 35-08, API # 05-071-09930; Location # 484676, active drilling location located in Las Animas County, Co  
CA's From Reclamation inspection # 713600094 still apply.  
Comply with Reclamation Inspection CA's and Dates.

**Location****Lease Road:**

Type	Access		
comment:	Vehicle rutting observed at the time of inspection		
Corrective Action:	Maintain vehicle tracking BMP's on the oil and gas location to comply with rule 1002.f. (2)F. Comply with rule 1002 f	Date:	09/25/2023

Overall Good: ☐**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash and Debris observed on location		
Corrective Action:	Comply with Rule 606.	Date:	09/25/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment observed on location		
Corrective Action:	Comply with rule 606	Date:	10/16/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

### Location Construction

Location ID: 484359 CDP: \_\_\_\_\_

Comment: Drill cuttings were not properly stored with a berm and liner as described in the waste management plan

Corrective Action: CA will maintain the original CA date of 8/15/2023 as outlined in Reclamation Inspection #713600094 on 8/15/2023

Date: 08/15/2023

#### Form 2A COAs:

Comment:

Corrective Action:

Date: \_\_\_\_\_

#### Wildlife BMPs:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Piles	Inadequate		
Comment	<p>Drill cuttings were not stored with berm and liner as described in the waste management plan. The cuttings pile still remains with no berm, liner, or other BMP. Previous corrective action was not completed.</p> <p>Drill cutting storage, handling, transport, and disposal must comply with Rule 905. Please also refer to 905.b. E&amp;P waste transportation for any offsite transportation of drill cuttings.</p>			
Corrective Action	Comply with Rule 905. for Management of E&P Waste			Date: 08/15/2023

**Spill/Remediation:**

Comment:	
Corrective Action:	Date: _____

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Comply with Rule 905. For Management of E&P waste	sanchezcc	09/15/2023
Subsidence noticed over top of pipe in Pipeline R-O-W; Operator shall adhere to Rule 1102.f.(2)	sanchezcc	09/15/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403533937	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255065">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255065</a>
710500012	710500010 Location Photos Red Rocks 35-08	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255056">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255056</a>