

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2023

Submitted Date:

09/27/2023

Document Number:

702501915

**FIELD INSPECTION FORM**

Loc ID 312957 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 83555  
Name of Operator: SUNBURST INC  
Address: P.O. BOX 140266  
City: EDEGEWATER State: CO Zip: 80214

**Findings:**

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor	(303) 894-2100, Ext 5164	conor.pesicka@state.co.us	
Jackson, Jay	(303) 781-3044	sun1045@aol.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

**General Comment:**

On Monday, 09/25/2023, Inspector Kirby Burchett, attempted to conduct a follow up field inspection at Sunburst Inc on the Cottonwood Gulch State A 1 well, Location #312957, in Moffat County, Colorado. This location is within or in close proximity to a CPW District with High Priority, NSO, and Density Habitat Regulations.

Any Corrective Actions from previous Inspections are still applicable.

Access gate off Moffat County road 22 is locked. Called emergency number listed on previous Inspection #702501379. (303) 870-9374 at 2:20 PM. Left a voicemail. Called company number, (303) 781-3044, listed on ECMC website at 2:22 PM . Same voicemail as emergency number. Now 48 hours past 2nd attempt has gotten no reply from Operator.

Previous attempt 1 week ago on 9/20/23 leaving a voicemail on the emergency number at 2:10 PM never got a call back.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Access is behind locked private gate. No location entrance sign for emergency services.		
Corrective Action:	The Location Entrance sign will identify: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available).	Date:	09/20/2023

Emergency Contact Number:	
Comment:	(303) 870-9374 Voicemail. No response.
Corrective Action:	Emergency number must be accessible at all times.
Date:	09/20/2023

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	