

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Access road to location**



**Entrance to location**

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Debris as in previous inspection**



**Erosion and sediment migration**

Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252



Debris remaining from previous inspection



Debris

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Staining from compressor**




**Staining from compressor**

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Erosion and sediment migration leaving location as in previous inspection**



**Erosion and sediment migration leaving location as in previous inspection**

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Erosion and sediment migration leaving location as in previous inspection**



**Insufficient Stormwater BMPs**

Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252



Insufficient Stormwater BMPs



Battery sign still missing required information

Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252



**Containment has not been repaired**



**Containment has not been repaired**

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Staining as in previous inspection**



**No wildlife protection still not resolved**

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Leaks and staining sill remain as in previous inspection**



**Same debris as in previous inspection**

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Same debris as in previous inspection**



**Same debris as in previous inspection**

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Same debris as in previous inspection**



**Same debris as in previous inspection**

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Location view from Southwest corner**



**Location view from Southeast corner**

**Foundation Energy Management LLC  
Lion Government 13-36  
Location ID: 313252**



**Location view from Northeast corner**



**Location view from Northwest corner**