

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

10/03/2023

Document Number:

709100111

FIELD INSPECTION FORM

 Loc ID 473986 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num:
Operator Information:

OGCC Operator Number: 10017

Name of Operator: CHACO ENERGY COMPANY

Address: P O BOX 1587

City: DENVER State: CO Zip: 80201

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

4 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel	303-817-5217	krystal.heibel@state.co.us	
Nelson, Kurt	(303) 744-1480	kurt@chacoenergy.com	All Inspections
Nelson, Alan	(405) 942-3751/ (405)623-7677	chaco@swbell.net	All Inspections

General Comment:

This is an environmental inspection of the Chaco Energy Company's Ziegler Tank Battery.

ECMC inspector Krystal Heibel arrived onsite on September 26, 2023, around 12:30 PM to perform an Environmental Inspection.

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

Location						
Lease Road:						
Type	Access					
comment:	Lease road well maintained					
Corrective Action:					Date:	
Overall Good: <input type="checkbox"/>						
Emergency Contact Number:						
Comment:	Sign not posted or information inaccurate at oil and gas location. Emergency contact number illegible from a distance.					
Corrective Action:	Install sign to comply with Rule 605.a.				Date:	11/03/2023
Good Housekeeping:						
Type						
Comment:	Unused equipment left onsite.					
Corrective Action:	Comply with Rule 606				Date:	11/03/2023
Overall Good: <input type="checkbox"/>						
Spills:						
Type	Area	Volume				
Crude Oil	Tank	<= 1 bbl				
Comment:	Hydrocarbon-stained soils observed around the tank battery.					
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.				Date:	11/03/2023
In Containment: No						
Comment:	<input style="width: 100%;" type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?						
Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	<input style="width: 100%;" type="text"/>					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate		
Comment:	Inadequate berms around tank(s). Large burrows observed.					
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date:	10/24/2023
Venting:						

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100112	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272401