

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2023

Submitted Date:

09/05/2023

Document Number:

699504975

FIELD INSPECTION FORMLoc ID 330652 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251613	WELL	PR	04/01/2017	OW	123-19416	EIBERGER 32-36	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment:

weeds unmanaged on location

Corrective Action:

Comply with rule 606

Date: 09/12/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

PUMP JACK

Comment:

6' chain link with barb wire only covers half of pump jack

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

1

Comment:

plumbed to surface

Corrective Action:

Date:

Type: Pump Jack

#

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Gas Motor

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 251613 Type: WELL API Number: 123-19416 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/02/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

ECMC Inspection Report Summary
 On 9/5/23 I, Inspector Justin Medina conducted an on-site inspection at:
 Well Name- Eiberger 32-36
 Company Name- KPK
 API- 05-123-19416
 In Weld County Colorado.
 While there, I observed PR well
 During this inspection the following possible compliance issues were observed:
 Weeds. Rule 606. 9/12/23
 A follow up on this site inspection needs to be conducted to ensure the compliance issues
 have been corrected to comply with ECMC rules.
 This inspection does not nullify any orders or corrective actions from the ECMC.
 This is a summary of inspection report.

medinaj

09/05/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504976	Inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272559