

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

10/03/2023

Document Number:

709100111**FIELD INSPECTION FORM**Loc ID 473986 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10017Name of Operator: CHACO ENERGY COMPANYAddress: P O BOX 1587City: DENVER State: CO Zip: 80201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Nelson, Kurt	(303) 744-1480	kurt@chacoenergy.com	All Inspections
Nelson, Alan	(405) 942-3751/ (405)623-7677	chaco@swbell.net	All Inspections
Krystal Heibel	303-817-5217	krystal.heibel@state.co.us	

General Comment:

[This is an environmental inspection of the Chaco Energy Company's Ziegler Tank Battery.](#)

[ECMC inspector Krystal Heibel arrived onsite on September 26, 2023, around 12:30 PM to perform an Environmental Inspection.](#)

[Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.](#)

Location

Lease Road:			
Type	Access		
comment:	Lease road well maintained		
Corrective Action:		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment: Sign not posted or information inaccurate at oil and gas location. Emergency contact number illegible from a distance.

Corrective Action: Install sign to comply with Rule 605.a.

Date: 11/03/2023

Good Housekeeping:

Type			
Comment:	Unused equipment left onsite.		
Corrective Action:	Comply with Rule 606	Date:	11/03/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	Tank	<= 1 bbl		
Comment:	Hydrocarbon-stained soils observed around the tank battery.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 11/03/2023

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Inadequate berms around tank(s). Large burrows observed.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 10/24/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403548958	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272417
709100112	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272401