

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2023

Submitted Date:

10/04/2023

Document Number:

699107488

### FIELD INSPECTION FORM

Loc ID 323364 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323364	LOCATION	AC			-	LOST CREEK STATE-64N62W 36SENW	AC

**General Comment:**

[Routine Inspection on the Tank Battery](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation throughout the location need to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/20/2023
Type	OTHER		
Comment:	Stained Soil next to the Vertical Heated Separator needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	10/20/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Gas Meter Run	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.270900,-104.274600
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	
Date:	

**Inspected Facilities**

Facility ID: 323364 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI Tank Battery

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b>                      On Tuesday 10/3/23 at approximately 0911hrs I, Inspector Adam Burns, Conducted an on-site inspection at Lost Creek State-64N62W 36SE1W Tank Battery of KP Kauffman Company INC.                      Location Id: 323364 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Overgrown vegetation throughout the location need to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 10/20/23                      Stained Soil next to the Vertical Heated Separator needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 10/20/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	10/04/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403550011	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273501</a>
699107489	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273479">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273479</a>